

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

MSB

Owner : Ngoh Chun Kiat (88368031)

*not Adul
n/c
28/1/22*

Accident Date : 14-Feb-22

Vehicle No : FBP3512L

*Repair sum
\$2600*

*2/5/22
3 days*

Vehicle Model : Yamaha
CZD300A /
Xmax 300

Estimated Repair Costs

the 2600 after repair

Qty	Description	Amount S(\$)
List Items		
1	Front fork assy <i>11</i>	\$ 980.00 <i>X</i>
1	Fork under bracket cover <i>11</i>	\$ 190.00 <i>X</i>
1	Front sport rim <i>11</i>	\$ 550.00 <i>X</i>
1	Front brake disc <i>11</i>	\$ 180.00 <i>X</i>
1	Front rim shaft <i>11</i>	\$ 52.00 <i>X</i>
1	Headlamp - LED <i>CU</i>	\$ 1,380.00 <i>—</i>
1	Side mirror <i>11</i>	\$ 180.00 <i>—</i>
1	Handle-bar <i>11</i>	\$ 135.00 <i>X</i>
1	Handle-bar balancer set <i>11</i>	\$ 125.00 <i>X</i>
1	Hand grip (1 set) <i>11</i>	\$ 60.00 <i>X</i>
1	Brake levers (1 set) <i>11</i>	\$ 150.00 <i>X</i>
1	Front cowling inner panel (1 set) <i>carbon</i>	\$ 300.00 <i>—</i>
1	Front inner panel <i>CU</i>	\$ 160.00 <i>X</i>
1	Front cover <i>CU</i>	\$ 440.00 <i>—</i>
1	Front fender <i>CU</i>	\$ 150.00 <i>—</i>
2	Front signals <i>1/5 AN 0/5 one</i>	\$ 150.00 <i>—</i>
2	Footstep panels <i>1/5 CU 0/5 CU</i>	\$ 310.00 <i>—</i>
1	Main stand <i>CU</i>	\$ 148.00 <i>—</i>
1	Side stand <i>R</i>	\$ 98.00 <i>X</i>
1	Air filter cover <i>SVC</i>	\$ 218.00 <i>X</i>
1	Belt cover <i>SUN</i>	\$ 180.00 <i>X</i>
1	Fairing cover (1 set) <i>CU/CU</i>	\$ 1,320.00 <i>—</i>
		\$ 7,456.00
	Less 10%	\$ 745.60
		\$ 6,710.40
Special Net Items		
2	Fork oils <i>11</i>	\$ 30.00 <i>X</i>
2	Fork oil seals <i>11</i>	\$ 56.00 <i>X</i>
1	Steering cone (1 set) <i>11</i>	\$ 120.00 <i>X</i>
1	Number plate (1 set) <i>11</i>	\$ 38.00 <i>X</i>
1	"X MAX" emblem <i>n/c</i>	\$ 80.00 <i>—</i>
		\$ 324.00 <i>60</i>

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Ngho Chun Kiat (88368031)

Accident Date : 14-Feb-22


Vehicle No : FBP3512L

Yamaha
Vehicle Model : CZD300A /
Xmax 300

Estimated Repair Costs

S/No.	Labour		
1	To provide towing service (LOD) S\$100.00	\$	-
2	To check wiring and reset headlamp focusing	\$	17 80.00 X
3	To provide labour	\$	300 480.00 400
4	To repair body frame	\$	17 450.00 X
5	To re-spray painting	\$	11 800.00 650
		\$	1,810.00 X
	Grand Total	\$	8,844.40

Singapore Dollars: Eight Thousand Eight Hundred Forty-Four and Cents: Forty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2803
P-2403
102
2900.7
202