

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 09 Mar 2022

Preliminary Advice

Insured Vehicle No : GX8823E
TP Vehicle No : FBP3512L
Make : YAMAHA CZD300A / XMAX300
Date of Inspection : 28/02/2022
Inspection At : EROFIA MOTOR TRADING PTE LTD - (KAKI BUKIT) (HQ)
1 KAKI BUKIT AVENUE 6, #02-62 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Accident Date : 14/02/2022
Assignment Date : 25/02/2022
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,844.40
Revised Amount	:S\$	2,900.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,900.70
Lump Sum Repair	:S\$	2,600.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	15,000.00
COE / PARF Rebate	:S\$	2,448.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,552.00

Remarks

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair

- The above survey was conducted on a 'without prejudice' basis.