



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22001838/Uqf3n2	
			Date: 08/03/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBR 1951E	Veh. Inspected	SLT 5555K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200720/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	25/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	BMW X1 S DRIVE (A)	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBAHS120605J97448	Colour	GREY
	Odometer	67970 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	PIRELLI	6 mm
	L/H Front Tyre	225/50 R18	PIRELLI	6 mm
	R/H Rear Tyre	225/50 R18	PIRELLI	6 mm
	L/H Rear Tyre	225/50 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/02/2022	Inspection Date	28/02/2022
	Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	