

⏪

<

1

of 2 ?

>

⏩

↺

↻

100%

▼

💾

✓

🖨

Find | Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

50 RAFFLES PLACE #03-03

SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO22001838/Uqf3

Date: 25/02/2022

Code: SMO

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBR 1951E	Veh. Inspected	SLT 5555K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2200720/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	25/02/2022

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	24/02/2022	Inspection Date	28/02/2022
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a.

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=345528&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1