



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GX5409M MITSUBISHI CANTER

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front panel logo badge <i>APC</i>		75.00	
1	Front panel emblem "CANTER" <i>APC</i>		100.00	
1	Front side top panel LH <i>DD</i>		739.00	
1	Center grille <i>CUT</i>		619.00	
1	Headlamp LH <i>BR</i>		584.00	
1	Side lamp LH <i>BR</i>		223.00	
1	Signal lamp LH <i>(1mc) - CUT</i>		237.00	
1	Front bumper <i>CRU</i>		444.00	
1	Front door outer lower garnish LH <i>MCJ</i>		209.00	
1	Front door lower signal lamp LH <i>CRA</i>		248.00	
1	Front door rubber seal LH <i>X DD</i>		58.00	
1	Front door weather strip LH <i>X DD</i>		416.00	
1	Front panel (Repair refer to labour) <i>X R</i>		0.00	
1	Front door LH (Repair refer to labour) <i>X R</i>		0.00	
Part Items Total:			3952.00	
			-25% -988.00	
			2964.00	
SPECIAL NETT ITEMS				
1	Front bumper clips <i>M</i>		35.00	
1	Front door company decal LH <i>MCJ</i>		25.00	
1	Front door company sticker LH <i>MCJ</i>		200.00	
2	Headlamp light bulb LH @Qty:02*\$25 <i>X DD</i>		50.00	
1	Side lamp light bulb LH <i>X DD</i>		25.00	
SN Items Total:			335.00	
Total Parts			3299.00	

3478
-25%
2608.50

195

LKI Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GX5409M MITSUBISHI CANTER

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	500
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	60.00	30
5	To remove, replace and focus headlamp beam	60.00	30
	Labour Total :	2180.00	
	TOTAL (PARTS & LABOUR):	5479.00	

L/S-3034.80
=3050

Steno (LKK)
8/3/22, 3.00

m AL
L/S
my AL y
3 dys