

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200064
Date: 24 Feb 2022
Veh Reg No: SND8306D
Make/Model: TOYOTA NOAH
HYBRID 7 SEATER 1.8X
CVT
Chasis No: ZWR800521687
Reg. Date: 26/01/2022
Your Ref No: SLF2460T

Claim Type: Third Party
Accident Date: 23/02/2022
TP Veh Reg No: SLF2460T

Xiao Tong

Estimate Repair Cost to Vehicle No :SND8306D

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC BOOT LID <i>Distorted</i>	1,894.60 ✓	
2	1 PC BOOTLID "HYBRID SYNERGY DRIVE" EMBLEM <i>new</i>	91.90 ✓	
3	1 PC BOOTLID LOGO <i>new</i>	101.60 ✓	
4	1 PC BOOT LID CHROME <i>cracked</i>	712.70 ✓	
5	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	143.40 +	
6	1 PC REAR WINDSCREEN RUBBER WITH GLASS <i>new new</i>	1,880.30 158	
7	1 PC BOOT LID OUTER OPENER HANDLE <i>new</i>	299.10 +	
8	1 PC BOOT LID LOCK <i>Distorted</i>	<u>663.10</u> 467.	
9	1 PC BOOT LID LOCK CHECKER <i>new</i>	55.60 +	
10	1 PC BOOT LID HOLDING HANDLE <i>new</i>	79.40 +	
11	2 PCS BOOTLID SIDE STOPPER <i>new</i>	122.80 +	
12	2 PCS BOOTLID SMALL STOPPER	49.20 +	
13	1 PC BOOT LID TRIM <i>cracked</i>	669.30 ✓	
14	1 PC BOOT LID RUBBER <i>cut</i>	367.90 ✓	
15	1 PC TAIL LAMP LH <i>cut</i>	<u>1,318.70</u> 781	
16	1 PC TAIL LAMP LOWER GARNISH LH <i>delnd</i>	296.10 ✓	
17	1 PC TAIL LAMP - RH <i>new cut</i>	<u>1,318.70</u> 781	
18	1 PC REAR PANEL <i>Distorted</i>	735.70 ✓	
19	1 PC REAR PANEL TRIM <i>delnd</i>	299.60 ✓	
20	1 PC REAR FENDER TRIM LH <i>delnd</i>	<u>897.90</u> ✓	
21	1 PC REAR FENDER TRIM RH <i>cracked</i>	<u>897.90</u> ✓	
22	1 PC SPARE TYRE PANEL <i>Regis</i>	825.20 +	
23	1 PC SPARE TYRE PANEL COVER BIG <i>cracked</i>	<u>928.90</u> 781.	
24	1 PC SPARE TYRE PANEL COVER SMALL <i>delnd</i>	212.10 ✓	
25	1 PC SPARE TYRE PANEL JACK BRACKET <i>new Best</i>	121.70 ✓	
26	1 PC SPARE TYRE PANEL TRIM <i>tom</i>	<u>669.20</u> 645 ✓	
27	1 PC REAR BUMPER <i>delnd</i>	1,080.10 ✓	
28	2 PCS REAR BUMPER SIDE RETAINER <i>cracked</i>	326.80 ✓	
29	1 PC REAR BUMPER REFLECTOR - LH <i>cracked</i>	78.90 ✓	

2pc rear Bumper retainer (long) *cracked*
197.20 x 2 = 394.40
150.

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200064
Date: 24 Feb 2022
Veh Reg No: SND8306D
Make/Model: TOYOTA NOAH
HYBRID 7 SEATER 1.8X
CVT
Chasis No: ZWR800521687
Reg. Date: 26/01/2022
Your Ref No: SLF2460T

Claim Type: Third Party
Accident Date: 23/02/2022
TP Veh Reg No: SLF2460T

Estimate Repair Cost to Vehicle No :SND8306D

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	12563.70 78.90	
31	1 PC REAR TOWING COVER <i>del</i>	9422.77 33.80	
32	1 PC REAR LH AIR DUCT COVER <i>new</i>	12782.70 111.20	
33	1 PC REAR ANTENNA SENSOR <i>encl</i>	9586.65 166.40	
		17,528.70	
	Less 25%	4,382.18	13,146.62

Special Net

34	1 PC REAR NUMBER PLATE <i>new</i>	50.00	+
35	1 PC REAR WINDSCREEN SEAL <i>3m</i>	60.00	30
36	1 PC REAR WINDSCREEN SEALANT	60.00	30
37	1 PC REVERSE CAMERA <i>new</i>	480.00	380
38	1 SET BOOT LID TRIM CLIPS <i>new</i>	40.00	30
39	1 SET TAIL LAMP LOWER GARNISH CLIPS <i>new</i>	40.00	20
40	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	20
41	1 SET REAR FENDER LH TRIM CLIPS <i>new</i>	60.00	30
42	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	60.00	30
43	1 PC SPARE TYRE PANEL CARPET <i>new torn</i>	300.00	150.200
44	1 SET REAR BUMPER CLIPS <i>new</i>	60.00	30
45	1 SET REVERSE SENSORS <i>new</i>	250.00	200
		1,500.00	1,500.00

Labour

46	1 TO CHECK WIRING	50.00	30
47	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
48	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
49	1 TO REMOVE AND REFIT INNER TRIM	200.00	60
50	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	50
51	1 TO REMOVE AND REFIT REAR EXHAUST PIPE	150.00	+
52	1 TO SPRAY UNDERSEAL	120.00	60
53	1 (REAR) TO SPRAY PAINTING	1,600.00	900

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2200064
Date: 24 Feb 2022
Veh Reg No: SND8306D
Make/Model: TOYOTA NOAH
HYBRID 7 SEATER 1.8X
CVT
Chasis No: ZWR800521687
Reg. Date: 26/01/2022
Your Ref No: SLF2460T

Claim Type: Third Party
Accident Date: 23/02/2022
TP Veh Reg No: SLF2460T

Estimate Repair Cost to Vehicle No :SND8306D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
54	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,200.00	900
55	1 TO REMOVE AND REFIX THIRD BRAKE LIGHT	80.00	x
		4,680.00	4,680.00
		Total	S\$ 19,326.62
		Add GST @ 7%	1,352.86
		Total Amount Payable	<u>S\$ 20,679.48</u>

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND SIX HUNDRED SEVENTY NINE AND CENTS FORTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair
- To describe damaged parts and repair
- Part prices are subject to quotation
- Third party survey is on "without prejudice" basis
- No verbal modification allowed
- Supplier of parts/items must be surveyed and approved by the Insurance Company

Accepted by Repairer

Signature:

Date:

Adrian Lij
Total: 12806.55 h/s 24/02/22

Total: 12806.55 Total: 12542.77
08 Days (P/P)