

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0715/2021/KS
DATE : 31-Aug-21
WIP : 42204

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Dear Adrian,
4 days ok.

OWNER'S NAME : MS LOW SIEW TEE SERENE MRS SERENE SORESENSEN
ADDRESS : 15 CASSIA DRIVE
SINGAPORE 289780
TELEPHONE : HP +65 96774880
TYPE OF CLAIM : OWN DAMAGED CLAIM
POLICY NO : 2000002749-01
VEHICLE NO : **SKE 688 J**
MODEL CODE : Q7 2.0 TFSI QU
MODEL YEAR : 20/1/2020
ENGINE NO : CYR 091811
CHASSIS NO : WAUZZZ4M7KD034346
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Aug-21
PLACE OF ACCIDENT : 1 WOODLIEGH LN. 357684

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKE 688 J.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 450.00	\$ 300.00
2	TO REMOVE AND RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER. TO RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,800.00	\$ 600.00
3	TO RESPRAY RHS REAR DOOR, DOOR COVER, RHS REAR FENDER, RHS REAR DOOR ARCH TRIM AND RHS REAR WHEEL ARCH TRIM.	\$ 3,500.00	\$ 1,800.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,942.00	\$ 2,892.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKE 688 J.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - RH	1	\$ 5,311.00	\$ 4,248.80
2	REAR DOOR OUTER SEAL - RH	1	\$ 250.00	\$ 200.00
3	BONDING AGENT	1	\$ 49.00	
4	CLEANING SOLUTION	1	\$ 68.00	
5	APPLICATOR	1	\$ 8.00	
6	REAR DOOR ATTACHMENT PARTS	1	\$ 99.00	
7	REAR DOOR CATCH - RH	1	\$ 105.00	
8	REAR DOOR SEAL, OUTER - RH	1	\$ 191.00	
9	SILL PANEL SEAL - RH	1	\$ 253.00	
10	REAR DOOR COVER - RH	1	\$ 600.00	\$ 479.60
11	REAR WHEEL ARCH COVER - RH	1	\$ 196.00	\$ 156.80
12	REAR WHEEL ARCH COVER - RH	1	\$ 377.00	\$ 301.20
13	SUNDRIES		\$ 300.00	\$ 7.84
TOTAL SPARE PARTS		:	\$ 7,807.00	\$ 5,394.24
TOTAL LABOUR CHARGES		:	\$ 5,942.00	\$ 2,892.00
GRAND TOTAL		:	\$ 13,749.00	\$ 8,286.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

BL-31/08/22