

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---------------------------------------|----------------|---------|-----------------------|--|
| | STRIDES AUTOM | OTIVE SERVICES PTE LTD | | Ref: | CS/SMR22001850/Uqf3n2 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 37705 | | Date: | 17/03/2022 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHB 602H | Veh. Inspected | | SMM 3371L | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/02/22/2067 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 28/02/2022 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | MITSUBISHI ATTRAGE (A) | c.c | | 1193 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2019 | |
| | Chassis No. | MMBSTA13AKH001531 | Colour | | RED | |
| | Odometer | 39989 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 185/55 R15 | YOKOHAMA | | 7 mm | |
| | L/H Front Tyre | 185/55 R15 | YOKOHAMA | | 7 mm | |
| | R/H Rear Tyre | 185/55 R15 | YOKOHAMA | | 7 mm | |
| | L/H Rear Tyre | 185/55 R15 | YOKOHAMA | | 7 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 23/02/2022 | Inspection Dat | е | 01/03/2022 | |
| | Survey held at | CYCLE & CARRIAGE.FULCO M | OTOR DEALER P | L | | |
| | | NO.330 UBI ROAD 3 SINGAPORE 408650 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORI | MAL PERIOD FOR REPAIR: | | 10 Worl | king Days | |
| | ESTIMATED NOR | WAL FERIOD FOR REPAIR. | | TO WOII | king Days | |