

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001851/BTY3N2**Date:** 17/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00053862101

Claimant Vehicle No : SGM1803S **Insured Vehicle No :** YP2862K

Date of Loss: 16/01/2022 Nature of Claim: TP Claim No: SNM22D201378/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM1803S**

Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR HID NAV (A) Engine No: A1251469N20B20B

Reg. Date: 26/09/2016 (Man. Year: 2016) Chassis No: WBA5A32060D829498

Colour: Black Odometer: 75457 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40ZR19 Rear Tyre Size: 275/35ZR19

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,530.79	1,812.67	4,718.12	72.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	860.00	1,990.00	69.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,380.79	2,672.67	6,708.12	71.51
Approved Total (Overridden) (\$\$)		2,150.00		
(\$\$)	9,380.79	2,150.00	7,230.79	77.08
+ GST 7.00/7.00% (\$\$)	656.66	150.50	506.16	77.08
Nett Amount (\$\$)	10,037.45	2,300.50	7,736.95	77.08

INSPECTION

Date of Assignment: 28/02/2022

Date Inspected: 28/02/2022 Inspected At: 160 SIN MING DR
#01-14 SIN MING AUTO CITY
SINGAPORE 575722
REPAIRER: TEAM AUTOPRO PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Mar 2022)

Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGM1803S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,524.00 FL	*1,150.00 FL
2	1		*REAR BUMPER CARRIER	No such part	671.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	312.00 FL	*122.70 FL
4	1		*REAR BUMPER INNER SPONGE	No such part	198.60 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Damaged	791.50 FL	*- FL
6	2		*REAR BUMPER BRACKET	No such part	450.00 FL	*- FL
7	1		*REAR BUMPER CENTRE BEAM	Broken	383.00 FL	*108.80 FL
8	1		*REAR BUMPER UNDER COVER	Broken	95.00 FL	*95.00 FL
9	1		*REAR BUMPER REVERSE SENSOR (4 Pcs)	Short Circuit (1 Pc only)	1,032.00 FL	*200.00 FL
10	1		*REAR END PANEL	Repair	849.00 FL	*- FL
11	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
12	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
13	1		*REAR BUMPER CARRIER CLIPS	Necessary	60.00 FS	*30.00 FS
14	4		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	240.00 FS	*160.00 FS
15	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
					Sub Total (\$\$)	6,846.10 1,896.50
					- List Item Discount on L Items 5.00/5.00% (\$\$)	315.31 83.83
					Total Parts (\$\$)	6,530.79 1,812.67

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR BUMPER REVERSE SENSOR	New	150.00	60.00
2	CHECK WIRING	New	120.00	0.00
3	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
4	CONDUCT WATER LEAK TEST	New	180.00	0.00
5	UPHOLSTERY	New	300.00	0.00
6	PANEL BEATING	New	800.00	400.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	800.00	400.00
Gross Labour Cost (\$\$)			2,850.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >