

TP Budget Direct SLN 84765 2017 May.
Xiao Chen. Mazda 3 1496cc

JM6BN22A8H0146875.

		1028.
Rear Bumper	Debond	1128.60 ✓
Rear Bumper Clips	MP	30(SN) ✓
Rear Bumper Side Holder x 02	MP	38 x 2 = 76 +
Rear Bumper Reflector x 02	MP	53.6 x 2 = 107.20 +
Rear Bumper Reinforcement	Det'd	564.20 ✓
Rear Sensor x 04	2 pieces damaged	205 x 4 = 820 ✓
Rear End Panel	Repair	530.40. +
Rear End Panel Top Garnish	MP	214.20 +
Rear End Panel Top Garnish Clips	MP	20(SN) +
Rear End Panel Sealant	MP	60(SN) +

2002.20

1605.76

S.N. 30

SLN 8476S.

Panel Beating.

Spray Painting.

Wiring

To remove reverse sensor

To spray tuff coat

To remove upholstery

~~800~~ 250

~~800~~ 300

~~52~~ 30

~~100~~ 50

150 +

640

150 +

total: 2271.76

L/S: 1.8K

02 Days.

1.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: