

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001857/DVY3S2**Date:** 24/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00239452100

**Claimant Vehicle No :** FBE6320L **Insured Vehicle No :** SGR3888H

Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: SNM22D201410/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **FBE6320L**

Make & Model: HONDA CBF150, 149cc (M) Engine No: KC11E2013009

Reg. Date: 15/07/2010 (Man. Year: 2010) Chassis No: LALKC11A2A3111018

Colour: Black Odometer: 51690 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 3.60 R18 Rear Tyre Size: 80/90 R18

Front Left Side: Maxxis 2 mm Rear Left Side: Maxxis 2 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,028.00	1,214.40	4,813.60	79.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	435.00	1,035.00	70.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,498.00</b>	<b>1,649.40</b>	<b>5,848.60</b>	<b>78.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>7,498.00</b>	<b>1,300.00</b>	<b>6,198.00</b>	<b>82.66</b>

**INSPECTION**

Date of Assignment: 08/03/2022

Date Inspected: 01/03/2022 Inspected At: Alfred Auto Services & Supplies (HQ)  
Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2  
Singapore 569538

Estimated Period of Repair: 3.0 days

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 24 May 2022)	
<b>Parts:</b>	N/A	HONDA CBF150 149cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBE6320L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLEBARS	Bent	220.00 F	*125.00 FL
2	1		*CLUTCH LEVER	Cut	128.00 F	*28.00 FL
3	1		*CLUTCH GRIP	Cut	105.00 F	*65.00 FL
4	1		*HEAD LAMP FAIRING	Cut	498.00 F	*185.00 FL
5	1		*SET FRONT FORKS	Not Necessary	989.00 F	*- FL
6	1		*SET FRONT CBF 150 STICKER	Necessary	210.00 F	*125.00 FL
7	1		*CENTRE SIDE FAIRING	Not Necessary	299.00 F	*- FL
8	1		*REAR FAIRING	Not Necessary	265.00 F	*- FL
9	1		*REAR FENDER	Deformed	298.00 F	*85.00 FL
10	1		*REAR TOOLBOX HOLDER BRACKET	Not Necessary	288.00 F	*- FL
11	1		*REAR BRAKE HUP	Not Necessary	495.00 F	*- FL
12	1		*REAR WHEEL SPORT RIM	Repair	520.00 F	*- FL
13	1		*REAR WHEEL SWING ARM	Bent	830.00 F	*420.00 FL
14	1		*REAR AXLE NUT COTTER PIN	Bent	198.00 F	*45.00 FL
15	1		*LH SIDE MIRROR	Cut	95.00 F	*50.00 FL
16	1		*LH SIDE SIGNAL	Cut	80.00 F	*38.00 FL
17	1		*REAR TOOLBOX (@ \$300.00 DISCOUNT 50%)	Cut	480.00 FS	*150.00 FS
18	1		*REAR NO PLATE	Bent	30.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,028.00</b>	<b>1,331.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	116.60
<b>Total Parts (\$\$)</b>	<b>6,028.00</b>	<b>1,214.40</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING.	New	120.00	0.00
2	TO REPAIR & RENEW, STRAIGHTENING, ADJUST ALL ACCIDENT AFFECTED AREA.	New	900.00	300.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED DAMAGED PARTS.	New	400.00	120.00
4	TO BALANCING SPORT RIM & RENEW TYRE.	New	50.00	15.00
<b>Gross Labour Cost (S\$)</b>			<b>1,470.00</b>	<b>435.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >