



**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

**INSURER : MS FIRST CAPITAL INSURANCE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2203/003
Policy No:	5122675697	Date of Loss:	04/03/2022
Vehicle Reg. No.:	<b>SGR512L</b>	Driveable?	no
Driver Age:	29/10/1965	Third Party Vehicle No.:	SMB86M
Any Injuries?	no	Contact No:	
Insured/Claimant:	WU XUEYU ANNA	Driver:	WU XUEYU ANNA

**PARTS MODEL**

Make/Model:	Hyundai, Veloster -	Vehicle Reg. Date:	04/03/2022
	KMHTC61DVDU112126		
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

**DESCRIPTION OF ACCIDENT/LOSS**

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

**COST OF CLAIMS**

	Amount
Parts	1,554.26
Miscellaneous Items	40.00
Labour	380.00
Paintwork Labour	500.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>2,474.26</b>
<b>GST 7.00%(S\$):</b>	<b>173.20</b>
<b>Nett Amount(S\$):</b>	<b>2,647.46</b>

This claim is handled by: Tee Shu yi

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

**INSURER : MS FIRST CAPITAL INSURANCE LTD****PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2203/003
Policy No:	5122675697	Date of Loss:	04/03/2022
Vehicle Reg. No.:	<b>SGR512L</b>	Driveable?	no
Driver Age:	29/10/1965	Third Party Vehicle No.:	SMB86M
Any Injuries?	no	Contact No:	
Insured/Claimant:	WU XUEYU ANNA	Driver:	WU XUEYU ANNA

**PARTS MODEL**

Make/Model:	Hyundai, Veloster - KMHTC61DVDU112126	Vehicle Reg. Date:	04/03/2022
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

**DESCRIPTION OF ACCIDENT/LOSS**

Description of Accident/loss REFER TO GIA REPORT

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

**COST OF CLAIMS**

	Amount
Parts	1,554.26
Miscellaneous Items	40.00
Labour	380.00
Paintwork Labour	500.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>2,474.26</b>
<b>GST 7.00%(S\$):</b>	<b>173.20</b>
<b>Nett Amount(S\$):</b>	<b>2,647.46</b>

This claim is handled by: Tee Shu yi



**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	704.16	-20.00	563.33 <i>de ✓</i>
2	1	REAR BUMPER LOWER	250.56	-20.00	200.45 <i>cut ✓</i>
3	1	REAR BUMPER REFLECTOR RH	109.26	-20.00	87.41 <i>✓</i>
4	1	REAR BUMPER RETAINER RH	74.25	-20.00	59.40 <i>✓</i>
5	1	REAR TAILLAMP RH	804.60	-20.00	643.68 <i>x</i>
<b>Total Parts (\$\$)</b>					<b>1,554.26</b>

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	40.00	0.00	40.00 <i>3 over ✓</i>
<b>Sub Total (\$\$)</b>					<b>40.00</b>

**Estimates On Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 <i>✓</i>
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	350.00	0.00	350.00 <i>200</i>
<b>Gross Labour Cost (\$\$)</b>					<b>380.00</b>

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	500.00	0.00	500.00 <i>220</i>
<b>Gross Labour Cost (\$\$)</b>					<b>500.00</b>

&lt; END OF ESTIMATES &gt;

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 9747549 / 62563561

WP 4/5/22 @ 1120

taufik@lkkauto.com

2 days

To check p/p or 4/5 repair  
Resurvey before (after) paint.