-	 	ш	DE	тΛ	11	2

E

Estima	ates On Parts				Control of the State of the Sta
No.	Qty	Particulars	Amount	%Disc	After Disc/
1	1	REAR BUMPER	678 878.40	-30.00	614.88
2	1	REAR BUMPER SIDE RETAINER RH	88.90	-30.00	62.23 XNY
3	1	REAR BUMPER SIDE RETAINER LH	88.90	-30.00	62.23 X v
4	1	REAR BUMPER INNER SPONGE	121.50	-30.00	85.05 Tha
5	1	REAR TAILGATE	17451,895.60	-30.00	1,326.92 bt
6	1	REAR TAILGATE INNER BOARD	337.50	-30.00	236.25 KNY
7	1	REAR TAILGATE LOGO	103.10	-30.00	72.17 Nel
8	1	REAR TAILGATE OUTER GARNISH	243.60	-30.00	170.52 x cm2
9	1	REAR OUTER GARNISH LAMP RH	378.10	-30.00	264.67 XMM
10	1	REAR OUTER GARNISH LAMP LH	378.10	-30.00	264.67 × ***
11	1	REAR WINDSCREEN SEALANT	108.90	-30.00	76.23
12	1	REAR END PANEL	650 877.50	-30.00	614.25 12 -
13	1	REAR END PANEL REINFORCEMENT	1,334.60	-30.00	934.22 X N7
14	1	REAR FLOOR PANEL	2,025.90	-30.00	1,418.13 RY
15	1	REAR FENDER LH 37	00.10 1,282.50	-30.00	897.75 XR
			Total Parts (S\$)		7.100.17

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER SENSOR	200.00	0.00	200.00 AU
2	1	REAR TAILGATE 70KM/H STICKER	60.00	0.00 30	60.00 ng
3	1	REAR TAILGATE NV200 EMBLEM	60.00	0.00	60.00 nes
4	1	REAR TAILGATE VANETTE EMBLEM	80.00	0.00	80.00 NU
5	1	REAR TAILGATE 6PAX STICKER	60.00	0.00 3 0	60.00 ner
6	1 .	REAR CAMERA	350.00	0.00	350.00 × ng

Sub Total (S\$) 810.00 400

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00 Go
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0,00	80.00 Zo
3	1	To Transfer Rear Tailgate,	80.00	0.00	80.00 60
4	1	To Dismantle and Refit Rear Windscreen Glass,	100.00	0.00	100.00
5	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,000.00	0.00	1,000.00 70.

No.	Qty	int Work Labour Particulars	Amount	%Disc	After Disc_
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,000.00	0.00	1,000.00 700

< END OF ESTIMATES >

Taufkin 97495749/6256356/

M2 4/3/21 C 1115

toufikh@/Manks.con

Fdays

Plp Resum after repair

July

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REAR TAILGATE RUBBER 242.00	954
REAR END PANEL TOP GARNISH 185.00	954
REAR TAILGATE INNER LOCK 3 5 480.00 -30.00 336.00 REAR TAILLAMP LH	954
REAR TAILLAMP LH	954
Total Parts (\$\$) 954.10	954
Total Parts (S\$) 954.10 12.23 cellaneous Items Particulars Amount %Disc After Disc Sub Total (S\$) abour Particulars Amount %Disc After	954
cellaneous Items Particulars Amount %Disc After Disc Sub Total (S\$) abour Particulars Amount %Disc After	954
cellaneous Items. Particulars Amount %Disc After Disc Sub Total (S\$) abour Particulars Amount %Disc After	
Particulars Particulars Amount %Disc After Disc Sub Total (S\$) abour Particulars Amount %Disc After	
Disc Sub Total (S\$) abour Particulars Amount %Disc After	
abour Sub Total (S\$)	
abour Particulars Amount %Disc After	
Particulars Amount %Disc After	0.
Dina	
DISC	
Gross Labour Cost (S\$)	0.
aint Work Labour	
Particulars Amount %Disc After	
Disc	

< END OF ESTIMATES >

\$700.10 1233 4933.10 20%-3453.17. 400 1680 P/p. \$5533.17 7days