

CONNECT3

566 Woodlands Road Singapore 597648

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L

GST: 53360061L

QT22/PA8051E/TPC

MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01
SGX Centre 2
Singapore 068807

2204.10

1110.00

3314.10

20%

2651.28

45-2,650

Dear Sir,

Cost of Repair to Vehicle PA8051E

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front bumper <i>scr /</i>	1	735.10	735.10 (637.30)
2.	Front bumper bracket LH ? <i>X an</i>	1	112.36	2938.80 112.36 X
3.	Front bumper clips <i>an /</i>	10	2.50	25% 25.00 ✓
4.	Front bumper inner duct <i>X an</i>	1	337.80	2204.10 337.80 X
5.	LH headlamp <i>cm /</i>	1	389.40	389.40 ✓
6.	LH passenger door <i>bt /</i>	1	1,887.10	1,887.10 ✓
7.	Spray painting	1	800.00	500 800.00
8.	Apply anti rust	1	50.00	30 50.00
9.	Check wiring	1	20.00	20.00
10.	Transfer door fittings	1	150.00	60 150.00
11.	Labour charges	1	1,000.00	400 1,000.00
SUB-TOTAL				500 55,506.76

- Price before 7% gst

Thank you.