

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Denise

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Attention : Motor Claim Department

Contact : 6389 6111 (main) Fax No. : 6222 1033

Estimate : TP22-025

Date : 25/02/2022

Vehicle Num. : SLE1983M

Make/Model : Honda Vezel-2016

Chassis/Eng# : RU31129490/LEB5079510

Accident Date : 25/02/2022

Claim No. :

Reference :

Policy No. : (11/07/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 pc	Rear Boot Lid <i>distorted</i>		1,286.70 1100
2.	2 pcs	Rear Boot Hinge L/R <i>new</i>	63.70	127.40 +
3.	1 pc	Rear Boot Lid Vezel Emblem		65.00 ✓
4.	1 pc	Rear Boot Lid Hybrid Emblem <i>3 new</i>		86.20 ✓
5.	1 pc	Rear Windscreen Moulding <i>new</i>		110.00 ✓
6.	1 pc	Rear Wiper Motor <i>new</i>		392.50 +
7.	2 pcs	Rear Boot Damper L/R <i>new</i>	165.00	330.00 ✓
8.	1 pc	Rear Boot Lid Weatherstrip <i>at and</i>		154.82 ✓
9.	1 pc	Rear Boot Lid Mechanism Lock		225.00 ✓
10.	1 pc	Rear Boot Lid Honda Logo <i>new</i>		64.20 +
11.	1 pc	Rear Boot Lid Inner Handle Cover <i>del</i>		71.50 ✓
12.	1 pc	Rear Boot Lid Inner Trim Board <i>new</i>		345.71 <i>756.40</i>
13.	2 pcs	Rear Boot Lamp L/R <i>RH at, LH unked</i>	378.20	756.40 378.20
14.	2 pcs	Rear Lamp L/R <i>at</i>	583.95	1,167.90 980
15.	2 pcs	Rear Side Bumper L/R <i>new</i>	251.78	503.56 +
16.	1 pc	Rear Fender Wheel Arc Guard Garnish LH <i>del</i>		283.80 185
17.	1 pc	Rear Bumper Assy <i>distorted</i>		392.60 765
18.	10 pcs	Rear Bumper Clips <i>new</i>	3.80	38.00 ✓
19.	2 pcs	Rear Bumper Side Holder L/R <i>new</i>	32.50	65.00 ✓
20.	2 pcs	Rear Bumper Bracket L/R <i>new</i>	25.00	50.00 +
21.	2 pcs	Rear Bumper Reflector Lamp L/R <i>new</i>	38.90	77.80 +
22.	1 pc	Rear End Panel <i>distorted</i>		642.50 <i>585</i>
23.	1 pc	Rear End Panel Inner Top Garnish <i>del</i>		98.70 ✓
24.	1 pc	Rear Tyre Panel Floor Panel <i>Reis</i>		918.60 +
25.	1 pc	Rear Tools Tray Garnish <i>new</i>		283.00 ✓
26.	1 pc	Rear Tyre Panel Cover Trim Board <i>new</i>		329.18 +
27.	2 pcs	Rear Fender Inner Trim Garnish L/R <i>new</i>	312.50	625.00 ✓
28.	1 pc	Rear Tyre Panel Lower Under Shield <i>del</i>		275.91 ✓
29.	6 pcs	Rear Tyre Panel Lower Under Shield Clips <i>new</i>	3.80	22.80 ✓

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Attention : Motor Claim Department

Contact : 6389 6111 (main) Fax No. : 6222 1033

Estimate : TP22-025

Date : 25/02/2022

Vehicle Num. : SLE1983M

Make/Model : Honda Vezel-2016

Chassis/Eng# : RU31129490/LEB5079510

Accident Date : 25/02/2022

Claim No. :

Reference :

Policy No. : (11/07/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1 pc	Rear Exhaust Silencer Box Assy <i>new</i>	613.80	613.80 +
		List Total S\$:		10,903.58
		20.00% Discount S\$:		2,180.72
				8,722.86
		SPECIAL NETT ITEMS :		
1.	1 pc	Windscreen Sealant <i>new</i>	40.00	40.00 -
2.	1 pc	Rear No. Plate w/frame <i>Best</i>	45.00	45.00 -
3.	1 set	Reverse Sensor <i>Damaged</i>	350.00	350.00 -
		Special Nett Total S\$:		435.00
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting	100.00	100.00 30
		To remove, instal upholstery, inner trim garnishes.	200.00	200.00 60
		To remove, instal exhaust & align pipe.	180.00	180.00 X
		To remove, replace & transfer rear boot lid components.	150.00	150.00 80
		To remove, replace rear windscreen.	200.00	200.00 120
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	1,800.00	1,800.00 80
		To putty and respray painting on affected area.	1,600.00	1,600.00 80
		Labour Total S\$:		4,230.00

Total S\$: 13,387.86

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adam Lj
1/3 28/02/22
068 up
Supplementary 88
total: 7741.43
1/3: 6.2K

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Attention : Motor Claim Department

Contact : 6389 6111 (main) Fax No. : 6222 1033

Supplementary Estimate : TP22025S

Date : 25/02/2022

Vehicle Num. : SLE1983M

Make/Model : Honda Vezel-2016

Chassis/Eng# : RU31129490/LEB5079510

Accident Date : 25/02/2022

Claim No. :

Reference :

Policy No. : (11/07/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 pc	LIST ITEMS : Buzzer <i>crushed</i>		110.00 ✓
		List Total S\$:		110.00
		20.00% Discount S\$:		22.00
				<u>88.00</u>

*Adrian L
M.S. 01/03/22*

Total S\$:	88.00
-------------	-------

=====

h
SUCCESS UNITED PTE LTD