



72/Amesbury St. #200, Springfield, MA 01105
Tel: (617) 558-4444 Fax: (617) 558-4444
E-mail: Y400538

Date : 23 FEB 2022

Attn: Motor Claims Department

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Date:

Job No. 2

Owner name : Komoco Car Rental

Date of Acc : 11/2/2022

Policy number : CN142622

Claim Type : 3rd Party Claim

Estimate

QTY	DESCRIPTION	UNIT	PRICE	AMOUNT
1	BUMPER CLIP X10 ? <i>Xnn</i>		86595-2T500	\$ 12.00
2	COVER-RR BUMPER <i>repair X</i>		86611-S1500	\$ 460.30
3	COVER-RR BUMPER LWR ? <i>Xnn</i>		86650-S1500	\$ 469.00
4	HOLDER-BACK WARING SYSTEM CTR, ? <i>Xnn</i>		86682-S1500	\$ 5.50
5	HOLDER-BACK WARING SYSTEM CTR, ? <i>Xnn</i>		86683-S1500	\$ 5.50
6	BEAM-RR BUMPER ? <i>Xnn</i>		86631-S1000	\$ 270.80
7	BRACKET-RR BEAM UPR MTG x2 ? <i>Xnn</i>		86633-S1500	\$ 10.60
8	BRACKET-RR BEAM LWR,CTR ? <i>Xnn</i>		86636-S1500	\$ 5.10
9	BRACKET-RR BEAM LWR MTG x2 ? <i>Xnn</i>		86637-S1500	\$ 10.20
10	STAY-RR BUMPER LH ? <i>Xnn</i>		86641-S1500	\$ 68.70
11	STAY-RR BUMPER RH ? <i>Xnn</i>		86642-S1500	\$ 68.70
12	SKID PLATE-RR BUMPER <i>cut ✓</i>		86671-S1600	\$ 1,078.90
13	MOULDING ASSY-RR BUMPER,CTRE <i>cut Xnn</i>		86696-S1500	\$ 39.50
14	WIRING HARNESS-RR BUMPER ? <i>Xnn</i>		91880-S1580	\$ 346.50
15	LAMP ASSY-REAR FOG <i>Xnn</i>		92406-S1610	\$ 669.30
16	LAMP ASSY-REAR FOG & R/REFL,LH <i>Xnn</i>		92405-S1610	\$ 669.30
17	LAMP ASSY-CENTER GARNISH ? <i>Xnn</i>		92409-S1500	\$ 201.20
18	ANTENNA ASSY-SMARTKEY <i>Xnn</i>		95420-J6400	\$ 41.90
19	ULTRASONIC SENSOR ASSY-P.A.S x2 <i>Xnn</i>		99310-S1500	\$ 367.20
				\$ 4,800.20
	Less 20% Discount			\$ 960.04
	Material total			\$ 3,840.16

Less 20% Discount

Material total

Estimate

1	To carry out accident body repair	\$	2,240.00	<u>320</u>
2	Complete putty and spray paint all affected areas	\$	1,960.00	<u>280 x mm</u>
	Total	\$	<u>8,040.16</u>	
	Excess			
	Add GST 7%			863.12

Grand Total

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***

RASUL
Hp 90010068

2 days

03/03/22 @ 11:30

P/p

Reswing before repair

email: casul@kkkauto.com