

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22001864/KTY3N2**Date:** 09/03/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005847	
Claimant Vehicle No :	SHB7502S	Insured Vehicle No :	SMW1261G	
Date of Loss:	25/02/2022	Nature of Claim:	TP	Claim No: M2200987

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7502S	Engine No:	2ZR2C18351
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDMKB3FU203080656
Reg. Date:	24/05/2019 (Man. Year: 2018)	Odometer:	250478 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,647.50	1,526.67	5,120.83	77.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,920.00	1,075.00	7,845.00	87.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,567.50	2,601.67	12,965.83	83.29
+ GST 7.00/7.00% (S\$)	1,089.73	182.12	907.61	83.29
Nett Amount (S\$)	16,657.23	2,783.79	13,873.44	83.29

INSPECTION

Date of Assignment:	28/02/2022	
Date Inspected:	25/02/2022	Inspected At: Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63 Singapore 569111
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$2,601.68

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB7502S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,REAR BUMPER	Buckled	442.60 FL	-	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 FL
3	1		*COVER,REAR BUMPER,LOWER	Serviceable	15.40 FL	-	*- FL
4	1		*GUARD,REAR BUMPER,CENTER	Bent	576.30 FL	-	*576.30 FL
5	1		*RETAINER,REAR BUMPER SIDE,LH	Distorted	116.50 FL	-	*116.50 FL
6	1		*RETAINER,REAR BUMPER SIDE,RH	Serviceable	117.70 FL	-	*- FL
7	1		*FILLER,REAR BUMPER EXTENSION,LH	Mtg Cracked	123.70 FL	-	*123.70 FL
8	1		*FILLER,REAR BUMPER EXTENSION,RH	Serviceable	123.70 FL	-	*- FL
9	1		*COVER,FLOOR UNDER NO 2 (RH)	Serviceable	241.90 FL	-	*- FL
10	1		*COVER,FLOOR UNDER NO 1 (LH)	Serviceable	175.10 FL	-	*- FL
11	1		*COVER,REAR FLOOR (CTR)	Serviceable	229.90 FL	-	*- FL
12	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	-	*- FL
13	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME,NO 2	Necessary	54.60 FL	-	*54.60 FL
14	1		*PLATE,BACK DOOR NAME,NO 1	Necessary	54.60 FL	-	*54.60 FL
15	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	-	*47.90 FL
16	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Serviceable	925.60 FL	-	*- FL
17	1		*COVER DECK TRIM,REAR	Serviceable	126.70 FL	-	*- FL
18	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	-	*- FL
19	1		*STAY ASSY,BACK DOOR,LH	Repair	242.50 FL	-	*- FL
20	1		*STAY ASSY,BACK DOOR,RH	Repair	242.50 FL	-	*- FL
21	1		*HINGE ASSY,BACK DOOR,LH	Repair	61.00 FL	-	*- FL
22	1		*HINGE ASSY,BACK DOOR,RH	Repair	61.00 FL	-	*- FL
23	1		*SET PARKING AID	Serviceable	700.00 FS	-	*- FS
24	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	-	*65.00 FS
25	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
27	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*- FS
28	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	-	*40.00 FS
29	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*- FS
30	1		*END PANEL TRIM CLIP	Necessary	65.00 FS	-	*- FS
31	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
32	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
33	1		*REAR NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	-	*- FS
34	1		*RR BUMPER ADVERTISEMENT	Necessary	100.00 FS	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **8,175.00** **1,963.90**
- List Item Discount on L Items 25.00/25.00% (\$\$) 1,527.50 437.23

Total Parts (\$\$) **6,647.50** **1,526.67**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	300.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	660.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			8,920.00	1,075.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >