

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7502S**

*Not Authored*  
*Recovery B4 paint*  
*2601-68*

**AAD2202-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**25 FEB 2022****SHB7502S**

JTDKB3FU203080656

200303878K

TOYOTA

PRIUS

25/02/2022

**SMW1261G/ Tokyo**

24/05/2019

PART		LIST	
1	COVER, REAR BUMPER	\$	<i>Rn</i> 442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>Rn</i> 332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$	<i>Rn</i> 15.40 X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Rn</i> 576.30 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	<i>Rn</i> 116.50 ✓
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Rn</i> 117.70 ✓
1	FILLER, REAR BUMPER EXTENSION, LH	\$	<i>Mycom</i> 123.70 ✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	<i>Rn</i> 123.70 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>Rn</i> 241.90 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>Rn</i> 175.10 X
1	COVER, REAR FLOOR (CTR)	\$	<i>Rn</i> 229.90 X
1	PANEL SUB-ASSY, BACK DOOR	\$	<i>Rn</i> 1,147.80 X
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	<i>Rn</i> 54.60 ✓
1	PLATE, BACK DOOR NAME, NO.1	\$	<i>Rn</i> 54.60 ✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	<i>Rn</i> 47.90 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	<i>Rn</i> 925.60 X
1	COVER, DECK TRIM, REAR	\$	<i>Rn</i> 126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>Rn</i> 650.30 X
1	STAY ASSY, BACK DOOR, LH	\$	<i>Rn</i> 242.50 X
1	STAY ASSY, BACK DOOR, RH	\$	<i>Rn</i> 242.50 X
1	HINGE ASSY, BACK DOOR, LH	\$	<i>Rn</i> 61.00 X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>Rn</i> 61.00 X
TOTAL		\$	<b>6,110.00</b>
25%		\$	<b>1,527.50</b>
		\$	<b>4,582.50</b>

**Special Nett**



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-

**SHB7502S**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	95.00	6500
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	4000
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1 END PANEL TRIM CLIP	\$	65.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	3000
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	3000
1 REAR NUMBER PLATE WITH MOULDING	\$	200.00	X
1 RR BUMPER ADVERTISEMENT	\$	100.00	5000
<b>TOTAL</b>	<b>\$</b>	<b>2,065.00</b>	

**TOTAL PARTS \$ 6,647.50****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 3000

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 500

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 480.00 X



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2202-

**SHB7502S**

To transfer of Fender fittings, attachments and perform water seepage test.	\$	na 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	na 250.00	X
Towing Fees	\$	na 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	6602
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	151
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	na 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>8,920.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>15,567.50</b>	

**(PART-BY-PART) Repair Days****25 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: