11 Allwind 28/1/22 1/5\$ (2000 Hodays

HSIAU TON

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No: 200006262D

VEHICLE No: FBK 3975K

LAR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u>
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

| | /3 | |
|------|---|-------------------|
| 1PC | FRONR FENDER CUT/DE 155 | \$325.00 |
| 1PC | HEADLAMP SCR EGO | \$1,100.00 |
| 1PC | FRONT WINDSHIELD 1 | \$280.00 🗶 |
| 2PCS | FRONT SIGNAL LAMPS @\$80.00 SV | \$160.00 🗶 |
| 1PC | FRONT FORK ASSY N/S SVC | \$1,990.00 |
| 1PC | FRONT FORK ASSY O/S Day of 1300 | \$1,990.00 |
| 1PC | FRONT FORK UNDER BRACKET べつ | \$685.00 🗙 |
| 1PC | FRONT FORK UPPER STEM | \$690.00 🗙 |
| 1PC | FRONT SPORT RIM | \$1,450.00 🗶 |
| 1PC | FRONT SPORT RIM SHAFT & | \$48.00 🔾 |
| 1SET | FRONT SPORT RIM STICKER AA | \$60.00 × |
| 1PC | FRONT BRAKE DISC O/S | \$515.00 🗶 |
| 1PC | BRAKE LEVER 647 136 | \$140.00 |
| 1PC | HANDLE BAR Suf 450 | \$520.00 |
| 1PC | HANDER BAR BALANCER O/S CA7 45 | \$80.00 |
| 1PC | HANDLE BAR GRIP O/S Au 60 | \$85.00 |
| 1PC | MIRROR O/S | \$100.00 × |
| 1PC | FUEL TANK COVER ASSY CM7 1100 | \$1,280.00 |
| 1SET | FUEL TANK COVER STICKER New | \$90.00 |
| 1PC | CLUTCH OUTER COVER O/S A 1 | \$490.00 X |
| 1PC | FRONT FOOT BRAKE PEDAL (1) | \$165.00 |
| 2PCS | FRONT FOOT REST SPORT @\$190.00 0 (5 Cu) 180 | \$380.00 (26 |
| 2PCS | FRONT FOOT REST BRACKET @\$165.00 Ols But 150 | \$330.00 1PC |
| 1PC | IU UNIT CUI | \$260.00 |
| 1PC | EXHAUST ASSY CUT/ Dyes 900 | \$1,200.00 |
| 2PCS | REAR FOOT REST @\$105.00 MS CU) US R | \$210.00 (8) |
| 2PCS | REAR FOOT REST @\$165.00 | \$330.00 × |
| 2PCS | REAR SIGNAL LAMPS @\$80.00 N/S SMO | \$160.00 176 |
| 1PC | REAR MUDGAURD Relong 165 | \$185.00 |
| 1PC | ENGINE BRACKET O/S Cre 140 | \$180.00 |
| 1PC | REAR LICENCE PLATE CM (1.02) | \$12.00 /0 |
| 1PC | FRONT LICENCE PLATE STICKER 17 | \$12.00 × |
| | | \$15,502.00 |
| | TO CHECK WIRING | 17 \$50.00 X |
| | TO STRAIGHTEN & REPAIR BODY FRAME | 11 \$450.00 × |
| | LABOUR FOR PANEL BEATING & REPLACED PARTS | \$400.00 300 |
| | TO SPRAY PAINTING | \$500.00 300 |
| | | TOTAL \$16,902.00 |

102 - 6291 - 102 1-1761-9 1-600