



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|------------|---------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD | | | Ref: | CS/CTI22001868/Tty3 |
| 3 ANSON ROAD #16-00 | | | Date: | 28/02/2022 |
| SPRINGLEAF TOWERSINGAPORE 079909 | | | Code: | CTI |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | PA 8049M | Veh. Inspected | SMC 6634L | |
| Policy No. | DMB1SNW00002082100 | Coverage (\$) | 0.00 | |
| Claim No. | SNM22D201363/C02/LEWLC | Excess (\$) | 0.00 | |
| Assign From | JENNY LEW | Assign Date | 28/02/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 24/02/2022 | Inspection Date | 28/02/2022 | |
| Survey held at | DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |