



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 2606J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR R/H	BENT	2,100.00	1,750.00
2	FRONT DOOR HINGE @\$167.00	LOWER DISTORTED	334.00	167.00
1	SIDE STEP PANEL R/H	DENTED / CUT	345.00	345.00
1	FRONT WHEEL ARCH TOP GARNISH	SERVICEABLE	410.00	-
1	FRONT BUMPER (BENT)	NOT CONSISTENT WITH THE IMPACT	1,308.00	-
1	SIDE LAMP R/H	BROKEN	257.00	257.00
1	HEADLAMP R/H	MTG CRACKED	555.00	555.00
1	HEADLAMP BRACKET R/H	SERVICEABLE	210.00	-
1	SIGNAL LAMP R/H	CRACKED	256.00	256.00
1	FRONT BUMPER BRACKET	TO REPAIR SEE LABOUR	205.00	-
1	MUDFLAP R/H	CUT	350.00	285.00
1	RADIATOR SPARE TANK	DENTED	350.00	238.00
	LESS 10% DISCOUNT		-668.00	-
	LESS 25% DISCOUNT		-	-963.25
			6,012.00	2,889.75
1	FRONT BUMPER PAD R/H	BUCKLED / CUT	380.00	259.00
	LESS 25% DISCOUNT		-	-64.75
			380.00	194.25
<u>SPECIAL NETT ITEMS</u>				
1	COMPANY STICKER & LOGO (SN)	NECESSARY	380.00	120.00
1	CANVAS R/H (SN)	TORN	550.00	480.00
1	FRONT RIM R/H (SN)	SERVICEABLE	450.00	-
			1,380.00	600.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT DAMAGE PARTS TO FACILITATE REPAIR.INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET.		1,800.00	500.00

Report Ref No. CS/SMR22001869/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT DAMAGED AREA AFFECTED.	NOT NECESSARY	1,600.00	500.00
	COMPUTER WHEEL ALIGNMENT.		80.00	-
	CHECK WIRING.		80.00	20.00
	TOP UP COOLANT.		80.00	20.00
			3,640.00	1,040.00
GRAND TOTAL			11,412.00	4,724.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CS/SMR22001869/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.