

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJQ 7558 D
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 30/01/2022

TP Veh Reg No: SGG3934R

Estimate No: ES2290214/YISHUN

Date: 08 Mar 2022

Policy No: 5109088605-02

Veh Reg No: SJQ7558D.1

Make/Model: TOYOTA TOYOTA VIOS
1.5 E (AUTO)

Chassis No: MR2B23F3701174916

Engine No: 2NRX437841

Reg. Date: 30/04/2019

Estimate Repair Cost to Vehicle No :SJQ7558D.1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	497.10	1 PC	497.10	✓
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
			518.10	
		Less 25%	129.53	388.58
Net Price				
3 REVERSE SENSORS	193.00	2 PCS	386.00	✓
			386.00	
		Less 10%	38.60	347.40
Labour				
4 REMOVE & REFIX REAR BUMPER ASSY, REVERSE SENSORS, TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT AND REALIGN THE SAME	300.00	1 LA	300.00	250
5 PUTTY & RESPRAY BOOT, REAR BUMPER, REAR PANEL, REINFORCEMENT	500.00	1 LA	500.00	400
			800.00	800.00
			Total	S\$ 1,535.98
			Add GST @ 7%	107.52
			Total Amount Payable	S\$ 1,643.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE