Id	<	1	of 2 ?	>	Þ١	\bigcirc	⊕	100%	~		Ġ	Find Next	
----	---	---	--------	---	----	------------	----------	------	---	--	---	-------------	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En Au	utomob	ile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD	R	ef:	CS3/SMR22001881/Vtf3						
	60 WOODLANDS E4SINGAPORE 75	INDUSTRIAL PARK 57705	D	ate:	28/02/2022						
			С	ode:	SMR						
	Policy Particulars :- (THIRD PARTY CLAIM)										
	Insured Veh.	SHB 5301T	Veh. Inspected		SKB 9462A						
	Policy No.		Coverage (\$)		0.00						
	Claim No.	TAX/02/22/2072	Excess (\$)		0.00						
	Assign From	HUA YEN	Assign Date		28/02/2022						
2.	Vehicle Particulars & Condition										
	Make & Model		c.c								
	Engine No.		Year of Reg.								
	Chassis No.		Colour								
	Odometer	KM	Steering								
	Brakes		Modification								
	General										
3.		Condit	ions of Tyres								
		Size	Make		Balance						
	R/H Front Tyre				mm						
	L/H Front Tyre				mm						
	R/H Rear Tyre				mm						
	L/H Rear Tyre				mm						
١.	Description of Damages										
5.		Genera	I Information								
	Accident Date	25/02/2022	Inspection Date								
	Survey held at										
5a.	Remarks										
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.										