



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : **ODWR**Vehicle No. : **GBH2792T**Make & Model : **CITROEN DISPATCH L1 1.6**Year of Manufacture : **2016**Chassis No. : **VF7VBBHSHGZ058652**Engine No. : **10JBHK0001046**Policy No. : **BVFCB0013732102**Time of Accident : **10:50HRS**Ins Company : **ALLIED WORLD**

Excess : _____

Date of Accident : **11.02.2022**

Suggested Days of Repair : _____

In-house Vehicle Assessor : _____

Repair EstimatesParts (a) Cost / List Price Items \$ **4,045.00**Plus/Less 10% \$ **404.50**Total of Cost / List \$ **4,449.50**(b) Nett Price Items \$ **-**

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ **365.00**Total Parts Cost (Appendix A) \$ **4,814.50**Labour (Appendix B) \$ **1,900.00**Total Repair Cost \$ **6,714.50**

The above total will be subjected to 7% G.S.T.

Case Owner : **ROHANI**

Signature : _____

Contact No : _____

*NOT Authorized
11 Day &
Penny After Pain
Ex @1500/*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Name of Surveyor : _____

Company : _____

Survey conducted on : **2/3/22** at **11am****Remarks By Surveyor**(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : **05** day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : **Le** Date: **2/3/22**

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : GBH2792T Case Owner : ROHANI
Make & Model : CITROEN DISPATCH L1 1.6 Year Manufacture : 2016
Chassis No : VF7VBBHSHGZ058652 Engine No : 10JBHK0001046
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : ODWR

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1	\$ 450.00				✓
2	Rear bumper clip	10	\$ 20.00				✓
3	LH Front Door	1	\$ 1,150.00				✓
4	LH Front Door Protector	1	\$ 85.00				✓
5	LH Rear Door	1	\$ 1,900.00				✓
6	LH Rear Door Protector	1	\$ 150.00				✓
7	LH Door Side Rubber seal	1	\$ 140.00				X
8	RH Rear Wheel Cover	1	\$ 150.00				✓
9	Company Sticker	1				\$ 15.00	✓
10	Wording Sticker-LOGO WARBURG	1		(check Inland or not)		\$ 350.00	?
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	6					
16	0	1					
17	0	1					
18	0	11					
19	0	1					
20	0	1					
21	0	1					
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Vehicle No.	: <u>GBH2792T</u>	Case Owner	: <u>ROHANI</u>
Make & Model	: <u>ITROEN DISPATCH L1 1.6</u>	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.