

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2792T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (WCP)	DENTED / CUT	450.00	450.00
10	REAR BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	LH FRONT DOOR (WCP)	BENT	1,150.00	1,150.00
1	LH FRONT DOOR PROTECTOR (WCP)	DENTED	85.00	85.00
1	LH REAR DOOR (WCP)	BENT	1,900.00	1,900.00
1	LH REAR DOOR PROTECTOR (WCP)	DENTED	150.00	150.00
1	LH DOOR SIDE RUBBER SEAL (WCP)	SERVICEABLE	140.00	-
1	RH REAR WHEEL COVER (WCP)	MISSING	150.00	150.00
	COST PLUS 10%		404.50	390.50
			4,449.50	4,295.50
	SPECIAL NETT ITEMS			
1	COMPANY STICKER (SN)	NECESSARY	15.00	15.00
1	WORDING STICKER - LOGO WARBURG (SN)	* CHECK	350.00	-
			365.00	15.00
	<u>LABOUR</u>			
	TO JACK, STRAIGHTEN REAR END PANEL, PANEL BEAT AND REPLACE.		1,000.00	540.00
	TO PUTTY, RESPRAY REAR BUMPER, FRONT DOOR, REAR DOOR AND AFFECTED AREAS.		800.00	540.00
	TO REMOVE AND REFIX STICKER.	* CHECK	100.00	-
	CHECK LIGHTING AND WIRING. (NPA)	NOT NECESSARY	-	-
	TRANSFER DOOR PART TO NEW DOOR (2 DOORS).		300.00	160.00
			2,200.00	1,240.00
	GRAND TOTAL		7,014.50	5,550.50

Report Ref No. CS/AWA22001886/Kqy3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$450.00 NETT)		5,550.50
LESS EXCESS		-1,500.00
NETT LIABILITY		4,050.50

Report Ref No. CS/AWA22001886/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser