

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001892/UTY3N2**Date:** 29/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00122942100

**Claimant Vehicle
No :** SMY7254C**Insured
Vehicle No :** SMU6295L

Date of Loss: 20/02/2022

Nature of Claim: TP

Claim
No: SNM22D201362/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMY7254C**

Make & Model: BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)

Engine No: B4390653N20B20B

Reg. Date: 26/09/2014 (Man. Year: 2013)

Chassis No: WBA5A32060D334833

Colour: White/Green

Odometer: 134835 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35R20

Rear Tyre Size: 245/35R20

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,602.05	3,792.75	6,809.30	64.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,520.00	2,750.00	64.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,872.05	5,312.75	9,559.30	64.28
Approved Total (Overridden) (\$\$)		4,250.00		
Nett Amount (\$\$)	14,872.05	4,250.00	10,622.05	71.42

INSPECTION

Date of Assignment: 28/02/2022

Date Inspected: 01/03/2022 Inspected At:

15 KAKI BUKIT ROAD 4
#01-05/53 BARTLEY BIZ CENTRE
REPAIRER: ZOOM AUTOWERKS PTE LTD

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2022)

Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY7254C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	95.40 FL	*- FL
2	1		*REAR TAILLAMP-RH	Not Necessary	655.00 FL	*- FL
3	1		*REAR BUMPER	Deformed/Torn	1,495.00 FL	*1,495.00 FL
4	1		*REAR BUMPER REFLECTOR	Not Necessary	115.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER	Not Necessary	139.95 FL	*- FL
6	1		*REAR DOOR RH	Bent/Warped	1,550.00 FL	*1,550.00 FL
7	1		*REAR WHEEL HUB	Not Necessary	221.00 FL	*- FL
8	1		*REAR WHEEL BEARING	Not Necessary	382.00 FL	*- FL
9	1		*REAR SHOCK ABSORBER	Not Necessary	496.00 FL	*- FL
10	1		*REAR KNUCKLE ARM	Not Necessary	1,089.00 FL	*- FL
11	1		*REAR CONTROL ARM	Not Necessary	456.00 FL	*- FL
12	1		*REAR LOWER ARM	Not Necessary	776.00 FL	*- FL
13	1		*REAR STAY ARM	Not Necessary	339.00 FL	*- FL
14	1		*REAR TOP ARM	Not Necessary	417.00 FL	*- FL
15	1		*REAR TRAILING ARM	Not Necessary	859.00 FL	*- FL
16	1		*REAR ALLOY WHEEL RIM-RH	Cut	1,210.97 FS	*850.00 FS
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
19	1		*REAR TYRE	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,056.32	3,945.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	454.27	152.25
Total Parts (\$\$)	10,602.05	3,792.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	350.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	200.00	40.00
7	PANEL BEATING	New	1,600.00	520.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00
Gross Labour Cost (\$\$)			4,270.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >