

Our Job Ref No : 305504346
Date : 11/02/22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr Thevan
Vehicle Reg No. : SHD4254S CTPL 09/0/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBL7039G
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$3,300.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : Ms. Loke YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD4254S

Date: 09/02/2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT BUMPER COVER			\$430.90	Cut
10	FRT BUMPER CLIPS			\$22.00	hec
1	FRT BUMPER SIDE BRACKER RH			\$28.00	hec
1	FRT BUMPER MOULDING CENTRE UPPER			\$368.50	scr
1	HEADLAMP RH			\$1,993.65	scr
1	DAY LIGHT RH			\$642.50	Cut
1	FRT BUMPER SIDE GRILLE RH			\$93.45	DIS
1	HEADLAMP SUPPORT PANEL			\$949.30	n. xSUC
1	FRT BUMPER AIR DUCT RH			\$153.80	n. xSUC
1	FRT FENDER RH			\$588.80	XV
1	FRT FENDER RETAINER BRACKET RH			\$41.40	hec
1	EMBLEM - BLUE DRIVE RH			\$26.60	hec
	SUB TOTAL			\$5,338.90	
	LESS 20%			\$1,067.78	
	DISCOUNTED TOTAL			\$4,271.12	
				\$-	nett
	Labour Charge				
	PANEL BEATING			\$1,050.00	700
	SPRAY PAINTING CHARGE			\$600.00	500
	CHECK ALL LIGHTING			\$60.00	20
	TOTAL LABOUR			\$1,710.00	
	ESTIMATE TOTAL			\$5,981.12	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuvan 82235769
 9/2/22 / 700
 LIS after repair photo
 3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: