



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206700

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 31/10/2022
Reference CC6/CTI22001897/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 7511U
Insured Veh. GBD 8243T
Claim No. SNM22D201425/C02
Policy No. DMCVSNW00057332105
Accident Date 25/02/2022
Inspection Date 28/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22001897/Apa3q2 Date: 31/10/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8243T	Veh. Inspected	GBJ 7511U	
Policy No.	DMCVSNW00057332105	Coverage (\$)	0.00	
Claim No.	SNM22D201425/C02	Excess (\$)	0.00	
Assign From		Assign Date	28/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VM20137004	Colour	GREY	
Odometer	70760 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	FALKEN	6 mm	
L/H Front Tyre	165/80 R14	FALKEN	6 mm	
R/H Rear Tyre	165/80 R14	FALKEN	6 mm	
L/H Rear Tyre	165/80 R14	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/02/2022	Inspection Date	28/02/2022	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7511U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	DENTED	2,155.30	1,635.00
1	REAR TAILGATE NISSAN LOGO	NECESSARY	120.00	65.00
1	REAR TAILGATE NV200 EMBLEM	NECESSARY	110.20	75.00
1	TAILGATE VANETTE EMBLEM	NECESSARY	110.00	68.00
1	TAILGATE MAX WEIGHT STICKER	NECESSARY	90.00	30.00
1	REAR TAILGATE LOCK	DAMAGED	320.50	262.00
1	REAR TAILGATE WEATHERSTRIPE	CUT	410.50	282.00
1	REAR TAILGATE NUMBER PLATE GARNISH	CRACKED	380.50	380.50
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	180.20	180.20
1	REAR BUMPER	DEFORMED	650.30	650.30
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	124.80	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	70.00	-
1	REAR BUMPER SPONGE	CRACKED	220.00	135.00
1	TAILLAMP RH	CRACKED	340.20	340.20
1	REAR END PANEL	DENTED	620.50	485.00
	LESS 10% DISCOUNT		-590.30	-458.82
			5,312.70	4,129.38
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	TAILGATE 70KM/H STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE 6 PAX STICKER (SN)	NECESSARY	20.00	10.00
1	TAILGATE ADVESTMENT STICKER (SN)	NECESSARY	420.00	300.00
1	TAILGATE OUTER CARBON STRIP (SN)	NECESSARY	200.00	100.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
			1,130.00	760.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,200.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	600.00

Report Ref No. CC6/CTI22001897/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF COAT.		250.00	60.00
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX TAILGATE WINDSCREEN.		140.00	120.00
	REMOVE & REINSTALL TAILGATE MECHANISM.		100.00	80.00
	REMOVE & REINSTALL REVERSE SENSOR.		80.00	50.00
			3,050.00	1,740.00
GRAND TOTAL			9,492.70	6,629.38

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00
---	--	--	--	-----------------

Report Ref No. CC6/CTI22001897/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 7511U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 7511U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

