

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 28/02/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBJ7511U		
MODEL	: NISSAN NV200		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 25-Feb-22
		TIME	: 14:55HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE <i>Dented</i>	1	\$ 2,155.30	\$ 2,155.30
2	REAR TAILGATE NISSAN LOGO	1	\$ 120.00	\$ 120.00
3	REAR TAILGATE NV200 EMBLEM	1	\$ 110.20	\$ 110.20
4	TAILGATE VANETTE EMBLEM	1	\$ 110.00	\$ 110.00
5	TAILGATE MAX WEIGHT STICKER	1	\$ 90.00	\$ 90.00
6	REAR TAILGATE LOCK	1	\$ 320.50	\$ 320.50
7	REAR TAILGATE WEATHERSTRIPE	1	\$ 410.50	\$ 410.50
8	REAR TAILGATE NUMBER PLATE GARNISH	1	\$ 380.50	\$ 380.50
9	REAR TAILGATE WINDSCREEN MOULDING	1	\$ 180.20	\$ 180.20
10	REAR BUMPER	1	\$ 650.30	\$ 650.30
11	REAR BUMPER SIDE RETAINER	2	\$ 62.40	\$ 124.80
12	REAR BUMPER TOWING COVER	1	\$ 70.00	\$ 70.00
13	REAR BUMPER SPONGE	1	\$ 220.00	\$ 220.00
14	TAILLAMP RH	1	\$ 340.20	\$ 340.20
15	REAR END PANEL	1	\$ 620.50	\$ 620.50

4588.20
4129.38

TOTAL PRICE	\$	5,903.00
LESS 10%	\$	590.30
SUB TOTAL PRICE	\$	5,312.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00
3	TAILGATE 70KM/H STICKER <i>new</i>	1	\$ 20.00	\$ 20.00
4	TAILGATE 6PAX STICKER <i>new</i>	1	\$ 20.00	\$ 20.00
5	TAILGATE ADVESTMENT STICKER <i>new</i>	1	\$ 420.00	\$ 420.00
6	TAILGATE OUTER CARBON STRIP <i>new</i>	1	\$ 200.00	\$ 200.00
7	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 200.00	\$ 200.00

760

TOTAL \$ 1,130.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	Tuff Coat	\$ 250.00	60	
4	WIRING CHECK	\$ 80.00	30	
5	TO REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 140.00	120	
6	ROMEVE & REINSTALL TAILGATE MECHANISM	\$ 100.00	80	
7	ROMEVE & REINSTALL REVERSE SENSOR	\$ 80.00	50	

1740

TOTAL

\$3,050.00

TOTAL PARTS COST : \$ 6,442.70
TOTAL LABOUR COST : \$ 3,050.00
TOTAL REPAIR COST : \$ 9,492.70

Adrian Lj
1/s 28/02/22.

06 days

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6625.38
4/s: 5312