

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0136/2022/JT
DATE : 25-Feb-22
WIP : 13425

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

5 days - ok - Jy - 22 Apr 22

OWNER'S NAME : MR CHAUDHARI AJAY ASHOK
ADDRESS : BLK 31 JURONG WEST ST 41
#04-30 THE LAKESHORE
SINGAPORE 649412
TELEPHONE : HP +65 90181837
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210004265-01
VEHICLE NO : **SMX 8267 P**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 30/01/2021
ENGINE NO : DEM 025744
CHASSIS NO : WAUZZZF53MA004285
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Feb-22
PLACE OF ACCIDENT : OPPOSITE INTERNATIONAL PLAZA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 8267 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$	3,000.00	\$	1,100.00
5	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	\$	520.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,992.00	\$	3,542.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 8267 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	\$ 1,994.40
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	\$ 234.00
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$ 120.40
8	FRONT BUMPER TRIM - RH	1	\$ 54.00	
9	FRONT BUMPER TRIM - CENTER	1	\$ 127.00	
10	RADIATOR GRILLE	1	\$ 1,881.00	
11	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$ 32.24
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
14	FRONT BUMPER TOP COVER	1	\$ 143.00	
15	"CAUTION" STICKER	1	\$ 16.00	
16	AIR COND STICKER	1	\$ 9.00	
17	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
19	POP RIVET	4	\$ 4.00	
20	FRONT PARKING AID SENSOR - OUTER	1	\$ 244.00	
SUB TOTAL SPARE PARTS		:	\$ 7,399.00	\$ 2,381.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 8267 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 2,381.04
21	FRONT PARKING AID SENSOR SEAL RING	4	\$ 13.00	
22	FRONT PARKING AID SENSOR SIDE	1	\$ 244.00	
23	FRONT FENDER - RH	1	\$ 1,189.00	\$ 951.20
24	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	
25	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	\$ 65.84
26	FRONT FENDER BRACKET - RH	1	\$ 41.00	
27	POP RIVET	5	\$ 19.00	
28	FRONT FENDER BRACKET - CENTER RH	1	\$ 55.00	
29	FRONT FENDER BRACKET - END RH	1	\$ 40.00	
30	FRONT FENDER BRACE - RH	1	\$ 132.00	\$ 105.20
31	FRONT FENDER TRIM - RH	1	\$ 171.00	\$ 136.40
32	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	\$ 238.80
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00	
34	FRONT WHEEL SPOILER - RH	1	\$ 82.00	\$ 65.12
35	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00	
36	HEADLIGHT MATRIX BEAM - RH	1	\$ 8,172.00	\$ 6,537.60
37	HEADLIGHT HOSE	1	\$ 42.00	
38	LIFT CYLINDER - RH	1	\$ 217.00	
39	LIFT CYLINDER BRACKET - RH	1	\$ 17.00	
40	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
SUB TOTAL SPARE PARTS		:	\$ 11,194.00	\$ 10,481.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 8267 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 10,481.20
41	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 40.00	
42	FRONT FENDER LEDGE COVER SHORT - RH	1	\$ 18.00	
43	HEADLAMPS COVER - RH	1	\$ 49.00	
44	ALUMINIUM RIM	1	\$ 1,889.00	
45	RUBBER VALVE	4	\$ 15.00	
46	FRONT NO PLATE	S/N	\$ 60.00	
47	RHS FRONT TYRE	S/N	TBC	\$ 340.00
48	SUNDRIES		\$ 300.00	\$ 33.28
TOTAL SPARE PARTS			: \$ 20,964.00	\$ 10,854.48
TOTAL LABOUR CHARGES			: \$ 6,992.00	\$ 3,542.00
GRAND TOTAL			: \$ 27,956.00	\$ 14,396.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT