

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 01 Mar 2022

Preliminary Advice

Vehicle No	: SDS6826Y	Accident Date	: 25/02/2022
Make	: AUDI A6	Policy No.	: 2100390817
Assignment Date	: 01/03/2022	Excess	: S\$400.00
Date of Inspection	: 28/02/2022	Est. Duration of Repair	: 4
Inspection At	: 24 BENOI SECTOR		
	REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 44,506.00
Revised Amount	:S\$ 11,897.00
Check Items (Estimated)	:S\$ 983.00
Total	:S\$ 12,880.00
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 61,000.00
COE / PARF Rebate	:S\$ 43,735.00
Salvage Value	:S\$
Margin for Repair	:S\$ 17,265.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.