

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6. 66 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0137/2022/JT
DATE : 25-Feb-22
WIP : 13365

Xiao Chen .

\$13108.40.

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN KOK KIONG ANDREW
ADDRESS : 24 JALAN HAROM SETANGKAI
SINGAPORE 258815
TELEPHONE : HP +65 96337330
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100390817-07
VEHICLE NO : SDS 6826 Y
MODEL CODE : AUDI A6 C7 2.0 TFSI MU
MODEL YEAR : 31/10/2014
ENGINE NO : CDN 410156
CHASSIS NO : WAUZZZ4G5EN154896
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Feb-22
PLACE OF ACCIDENT : SLIP ROAD AT HOLLAND ROAD AND
NORTH BUONA VISTA ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDS 6826 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250 500 H.S.
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 1,700.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	500 ✓
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00	100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,472.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6766 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 6826 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>	1 S	3,012.00 ✓	2409.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	287.00 ✓	
3	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1 S	212.00 ✓	
4	FRONT BUMPER SPOILER <i>new</i>	1 S	276.00 ✓	
5	FRONT BUMPER TRIM COVER <i>new</i>	1 S	111.00 ✓	
6	FRONT BUMPER END CAP SET <i>new</i>	1 S	160.00 ✓	
7	RADIATOR GRILLE <i>Smoked</i>	1 S	1,478.00 ✓	1182.40
8	RADIATOR GRILLE CENTER COVER <i>Discol'd</i>	1 S	41.00 ✓	32.24
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 S	342.00 ✓	
10	FRONT BUMPER END CAP - LH <i>new</i>	1 S	44.00 ✓	
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1 S	111.00 ✓	88.80
12	FRONT BUMPER REINFORCEMENT BEAM <i>But</i>	1 S	927.00 ✓	741.20
13	FRONT BUMPER BRACKET HOLDER - LH / RH <i>new</i>	2 S	582.00 X	
14	FRONT BUMPER BRACE - LH / RH <i>new</i>	2 S	68.00 X	
15	POP RIVET <i>new</i>	4 S	4.00 X	
16	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 S	29.00 X	
17	FRONT BUMPER GUIDE PIECE - LH / RH <i>new</i>	2 S	84.00 ✓	
18	FRONT BUMPER TOP COVER <i>new</i>	1 S	137.00 ✓	109.60
19	"CAUTION" STICKER <i>new</i>	1 S	16.00 ✓	12.40
20	AIR COND STICKER <i>new</i>	1 S	34.00 ✓	26.96
SUB TOTAL SPARE PARTS			: \$ 7,955.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 6826 Y

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT PARKING AID SENSOR <i>Not n</i>	2	S	488.00	+	
22	FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER <i>n</i>	4	S	6.00	+	
23	FRONT BUMPER WIRING SRT	1	S	642.00	+	
24	HORN - LH / RH	2	S	502.00	+	
25	HORN BRACKET - LH / RH	2	S	102.00	+	
26	BONNET	1	S	5,736.00	+	
27	BONNET ATTACHMENT PARTS	1	S	150.00	+	
28	BONNET LOCK BAR	1	S	56.00	+	
29	BONNET LOCK MICRO-SWITCH	1	S	228.00	+	
30	BONNET BOWDEN CABLE COVER	1	S	4.00	+	
31	BONNET BOWDEN CABLE - CENTER	1	S	64.00	+	
32	BONNET RELEASE CABLE COVER	1	S	11.00	+	
33	BONNET CATCH HOOK - LOWER	1	S	20.00	+	
34	BONNET CATCH HOOK - UPPER	1	S	155.00	+	
35	BONNET LOCK CABLE	1	S	82.00	+	
36	FRONT WHEEL HOUSING LINER - LH / RH	2	S	670.00	+	
37	FRONT WHEEL SPOILER - LH / RH	2	S	588.00	+	
38	HEADLIGHT MOUNTING - LH / RH	2	S	264.00	+	
39	HEADLIGHT - LH / RH <i>LH ok ; RH cracked</i>	2	S	7,056.00	+	5652.80
40	LIFT CYLINDER - LH / RH <i>Not n</i>	2	S	518.00	+	
SUB TOTAL SPARE PARTS			:	\$	17,302.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 6826 Y

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	HEADLIGHT WASHER ASSY COVER CAP - LH / RH <i>new</i>	2	\$ 128.00	+	
42	HEADLIGHT HOSE <i>new</i>	1	\$ 43.00	+	
43	LOCK CARRIER <i>new</i>	1	\$ 1,385.00	+	
44	LOCK CARRIER BRACKET - LH / RH <i>new</i>	2	\$ 83.00	+	
45	A/C CONDENSER <i>new</i>	1	\$ 829.00	+	
46	REFRIGERANT HOSE	1	\$ 286.00	+	
47	REFRIGERANT PIPE	1	\$ 286.00	+	
48	PRESSURE SENDER	1	\$ 206.00	+	
49	HIGH PRESSURE SWITCH	2	\$ 104.00	+	
50	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 26.00	+	20.40
51	CHARGE AIR COOLER	1	\$ 628.00	+	
52	PULSATION DAMPER	1	\$ 88.00	+	
53	PRESSURE HOSE	1	\$ 76.00	+	
54	RADIATOR	1	\$ 804.00	+	
55	RADIATOR TWIN FAN RING	1	\$ 288.00	+	
56	RADIATOR FAN - LH	1	\$ 880.00	+	
57	RADIATOR FAN - RH	1	\$ 781.00	+	
58	RADIATOR FAN CONTROL UNIT	1	\$ 842.00	+	
59	RADIATOR COOLANT	6	\$ 282.00	+	
60	RADIATOR AIR GUIDE - LH / RH <i>new</i>	2	\$ 194.00	+	
SUB TOTAL SPARE PARTS			:	\$ 8,239.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NDRA.KHAJ@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDS 6826 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	RADIATOR GRILLE AIR GUIDE - UPPER	1	\$	32.00	✓
62	RADIATOR GRILLE AIR GUIDE - LOWER	1	\$	25.00	✓
63	AIR INTAKE HOSE	1	\$	31.00	✓
64	INTAKE AIR GUIDE	1	\$	90.00	✓
65	FRONT NO PLATE	S/N	\$	60.00	✓
66	SUNDRIES		\$	300.00	✗
TOTAL SPARE PARTS		:	\$	34,034.00	
TOTAL LABOUR CHARGES		:	\$	10,472.00	
GRAND TOTAL		:	\$	44,506.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Li
28/02/22

Not Authorized, 04 days 88/8.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT