

ESTIMATE*

VEHICLE NO SHB6628U

DATE 27/02/22

MAKE REG.30.10.2019

MODEL : HYUNDAI IONIQ G3

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH			\$35.00 <i>Run</i>
1	FRONT BUMPER			\$430.90 <i>de</i>
1	HEADLAMP LH			\$1,993.65 <i>nt</i>
1	FOG LAMP LH			\$642.50 <i>X hn</i>
1	FRONT BUMPER GARNISH LH			\$186.90 <i>X nn</i>
1	FRONT FENDER SHIELD LH			\$164.70 <i>Run.</i>
1	FRONT FENDER LH			\$588.80 <i>pt</i>
1	FRONT FENDER EMBLEM			\$26.60 <i>ue</i>
1	FRONT WHEEL COVER LH			\$346.40 <i>nt</i>
	SUB TOTAL		3386.35	\$4,415.45
	20.00%		2709.08	\$883.09
	DISCOUNTED TOTAL			\$3,532.36
1	FRONT FENDER ADVERTISEMENT		100	\$100.00 <i>ue</i>
	Labour Charge			\$100.00
	Panel Beating			\$700.00 <i>525</i>
	Spray Paint		1115	\$600.00 <i>500</i>
	Reset Wheel alignment			\$60.00 <i>✓</i>
	Check lighting			\$90.00 <i>30</i>
	TOTAL LABOUR		3924.08	\$1,450.00
	ESTIMATE TOTAL		16593.00	\$5,082.36
	<i>Repair 22445749</i>		<i>3 days</i>	
	<i>up 28/2/22</i>		<i>*</i>	
	<i>temp effluents on</i>			
	<i>2-3 days</i>			
	<i>4/5 Kmsy after repair.</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.		LKK Auto Consultants hence notify the Repairer of the following:		
		<ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 		
		Acknowledged by Repairer		
		Signature:		
		Date:		