



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188

LKK A to Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To notify damaged part(s) during resurvey
- To be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TP/PS



TOYOTA

Not Allowed
Tehuph-Schweipaly.
1/3/22
12 days

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM <i>Vehicle Grounded liability</i> <i>At New Scheme</i>		S1000020 / TPCLAIM	Mr Yong Pui Chong				
		Document No. 0	10D Braddell Hill #10-13 Singapore 579723				
		Document Date 28/02/2022	Mobile: 91997153				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SMC3498H ACC DATE:28/02/2022 TP INS: NO.OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR BONNET				60.00	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00	
4	B	BP-MECH2 R/I AIRCON CONDENSER/RADIATOR TO FACILITATE REPAIRS.			17	360.00	
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				122.40	
6	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. <i>720 x 3</i> STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.			2160	4320.00	
7	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS. <i>890 x 3</i>			1770	3540.00	
8	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR BOOTLID AND REAR END PANEL.			120	120.00	
9	B	BP-LAB2 TO CONDUCT WATER LEAK TEST.				122.40	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			Less		
			Parts Labour Sublet Lubrication/Fluid Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153
	Document No. 0	
	Document Date 28/02/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS.				180.00
11	B	BP-LAB2 R/I REAR CARPET,TRIMMING AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				360.00
12	B	BP-LAB2 TO TRANSFER REAR BOOTLID MECHANISM AND COMPONENT TO NEW PANELS.				360.00
13	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. <i>710 x 4</i>			<i>2880</i>	4320.00
14	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS. <i>590 x 4</i>			<i>2360</i>	3540.00
15	1	S81110-0DF50 HEADLAMP ASSY, RH <i>holder one</i>	1.00	1668.80		1668.80
16	2	S81150-0DF50 HEADLAMP ASSY, LH <i>holder one</i>	1.00	1668.80		1668.80
17	3	S85315-0D220 JAR, WASHER, A <i>11</i>	1.00	154.60		154.60
18	4	S88300-0D530 AIR CON KIT (NEW VIOS 2016) <i>11</i>	1.00	3026.60		3026.60
19	5	S08889-80102 COOLANT,SLLC&& <i>11</i>	2.00	84.30		168.60
20	6	S16400-0Y191 RADIATOR ASSY <i>11</i>	1.00	2176.50		2176.50
21	7	S53112-0D650 GRILLE, RADIATOR, LW <i>2.5</i>	1.00	387.30		387.30
22	8	S53113-0D020 GRILLE, RADIATOR, LW <i>2.5</i>	1.00	96.60		96.60
23	9	S52119-0U932 COVER, FR BUMPER, L <i>2.5</i>	1.00	525.80		525.80
24	0	S52161-0K040 CLIPS <i>nee</i>	4.00	4.30		17.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153
	Document No. 0	
	Document Date 28/02/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	1	S52535-0D230 RETAINER, FR BUMPER <i>Sub</i>	1.00	106.70		106.70
26	2	S52536-0D230 RETAINER, FR BUMPER <i>Sub</i>	1.00	106.70		106.70
27	3	T90467-05170 CLIP <i>Sub</i>	2.00	2.70		5.40
28	4	T47749-33030 CLIP, PIN HOLD <i>Sub</i>	2.00	9.20		18.40
29	5	T53879-33030 RETAINER, FR FENDER <i>Sub</i>	2.00	12.80		25.60
30	6	S52021-0D140 REINFORCEMENT SUB-AS <i>R</i>	1.00	423.90	X	423.90
31	7	S53111-0D912 GRILLE, RADIATOR, OU <i>Sub</i>	1.00	75.40		75.40
32	8	S53123-0D050 MOULDING, RADIATOR G <i>Sub</i>	1.00	73.40		73.40
33	9	S53124-0D040 MOULDING, RADIATOR G <i>Sub</i>	1.00	73.40		73.40
34	0	S53119-0D010 PROTECTOR, RADIATOR <i>Sub</i>	1.00	15.50	X	15.50
35	7	T53119-12150 FRT GRILLE CUSHION, <i>Sub</i>	2.00	20.90	X	41.80
36	2	S90975-T2008 EMBLEM, SYMBOL <i>Sub</i>	1.00	61.90		61.90
37	3	S53301-0D280 HOOD SUB-ASSY <i>Sub</i>	1.00	982.10		982.10
38	4	S53510-0D770 LOCK ASSY, HOOD <i>Sub</i>	1.00	143.70	X	143.70
39	5	S53410-0D400 HINGE ASSY, HOOD, RH <i>Sub</i>	1.00	62.40	X	62.40
40	6	S53420-0D400 HINGE ASSY, HOOD, LH <i>Sub</i>	1.00	62.40	X	62.40
41	7	S53141-0D040 COVER, RADIATOR <i>Sub</i>	1.00	290.40	X	290.40
42	8	T90467-07217 CLIP <i>Sub</i>	10.00	2.70		27.00
43	9	S53208-0D901 SUPPORT SUB-ASSY, HO <i>Sub</i>	1.00	159.30	X	159.30
44	0	S53210-0D929 SUPPORT ASSY, RADIAT <i>R</i>	1.00	1034.50	X	1034.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153
	Document No. 0	
	Document Date 28/02/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
45	1	S53213-0D161 SUPPORT, RADIATOR, U <i>11</i>	1.00	83.60	<i>X</i>	83.60 <i>X</i>
46	2	S53214-0D161 SUPPORT, RADIATOR, U <i>11</i>	1.00	83.60	<i>X</i>	83.60 <i>X</i>
47	3	S53285-0D370 SEAL, RADIATOR SIDE <i>11</i>	1.00	84.70	<i>X</i>	84.70 <i>X</i>
48	4	S53286-0D370 SEAL, RADIATOR SIDE <i>11</i>	1.00	84.70	<i>X</i>	84.70 <i>X</i>
49	5	S53287-0D260 EXTENSION, RADIATOR <i>11</i>	1.00	68.40	<i>X</i>	68.40 <i>X</i>
50	6	S53288-0D250 EXTENSION, RADIATOR <i>11</i>	1.00	76.60	<i>X</i>	76.60 <i>X</i>
51	7	SPC507-0D015 43 BACK SENSOR 218 ATTITUDE BLACK <i>shunt</i>	1.00	198.50	<i>X</i>	198.50 <i>X</i>
52	8	TAUTOF-J3W11 BACK CAMERA <i>11</i>	1.00	217.85	<i>X</i>	217.85 <i>X</i>
53	9	S81550-0DA41 LAMP ASSY, RR <i>RM Daged</i>	1.00	676.20	<i>X</i>	676.20 <i>X</i>
54	0	S81560-0DA41 LAMP ASSY, RR <i>11</i>	1.00	676.20	<i>X</i>	676.20 <i>X</i>
55	1	S52562-0D130 RETAINER, RR BUMPER, <i>one</i>	1.00	63.40	<i>X</i>	63.40 <i>X</i>
56	2	S52563-0D130 RETAINER, RR BUMPER, <i>one</i>	1.00	63.40	<i>X</i>	63.40 <i>X</i>
57	3	T81496-60010 REAR LAMP GUIDE, <i>11</i>	2.00	3.70	<i>X</i>	7.40 <i>X</i>
58	4	S81497-0D070 COVER, RR COMBINATIO <i>11</i>	2.00	3.50	<i>X</i>	7.00 <i>X</i>
59	5	S81580-0D490 LAMP ASSY, RR, RH <i>11</i>	1.00	438.10	<i>X</i>	438.10 <i>X</i>
60	6	S81590-0D490 LAMP ASSY, RR, LH <i>11</i>	1.00	438.10	<i>X</i>	438.10 <i>X</i>
61	7	S81910-0D050 REFLECTOR ASSY, REFL <i>RM one</i>	1.00	99.80	<i>X</i>	99.80 <i>X</i>
62	8	S81920-0D050 REFLECTOR ASSY, REFL <i>11</i>	1.00	99.80	<i>X</i>	99.80 <i>X</i>
63	9	T89997-30100 ANTENNA, ELECTRICAL <i>11</i>	1.00	76.30	<i>X</i>	76.30 <i>X</i>
64	0	S52159-0U963 COVER, RR BUMPER L/C <i>one</i>	1.00	557.70	<i>X</i>	557.70 <i>X</i>

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153
	Document No. 0	
	Document Date 28/02/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
65	1	S75895-0D270 TAPE, MOULDING, NO.1 <i>nee</i>	2.00	53.50		107.00 ✓
66	2	S52161-0K040 CLIPS <i>nee</i>	4.00	4.30		17.20 ✓
67	3	S52575-0D340 RETAINER, RR BUMPER <i>nee</i>	1.00	164.30		164.30 ✓
68	4	S52576-0D330 RETAINER, RR BUMPER <i>nee</i>	1.00	164.30		164.30 ✓
69	5	S52023-0D090 REINFORCEMENT SUB-AS <i>nee</i>	1.00	353.10		353.10 ✓
70	6	S58311-0D111 PAN, RR FLOOR <i>nee</i>	1.00	739.90		739.90 ✓
71	7	S58307-0D480 PANEL SUB-ASSY, BODY <i>nee</i>	1.00	786.30		786.30 ✓
72	8	S58387-0D200 PLATE, RR FLOOR FINI <i>nee</i>	1.00	295.40		295.40 ✓
73	9	T90467-08186 C3 CLIP <i>nee</i>	2.00	2.60		5.20 ✓
74	0	S64770-0D380 COVER ASSY, SPARE WH <i>nee</i>	1.00	322.90		322.90 ✓
75	1	S64401-0D360 PANEL SUB-ASSY, LUGG <i>nee</i>	1.00	838.90		838.90 ✓
76	2	S64461-0D180 WEATHERSTRIP, LUGGAG <i>nee</i>	1.00	186.50		186.50 ✓
77	3	S64600-0D040 LOCK ASSY, LUGGAGE C <i>nee</i>	1.00	423.90		423.90 ✓
78	4	S75431-02090 LUGGAGE COMP EMBLEM, <i>nee</i>	1.00	65.30		65.30 ✓
79	5	S75442-0D400 PLATE, LUGGAGE COMPT <i>nee</i>	1.00	48.30		48.30 ✓
80	6	S75444-0D700 PLATE, LUGGAGE COMPT <i>nee</i>	1.00	37.60		37.60 ✓
81	7	S76801-0D870 GARNISH SUB-ASSY, BA <i>nee</i>	1.00	65.20		65.20 ✓

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	39,997.25	
 	Please acknowledge receipt of vehicle 	Parts	22,382.45	GST 7.00%	2,799.81
		Labour	17,614.80		
		Sublet	0.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	42,797.06

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

Supplementary
ESTIMATE

Account Details		Account No. S1000006 / ICIII1		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		Document No. 0		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723				
		Document Date 10/03/2022		Mobile: 91997153				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	01/03/2022 15.07		10/03/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	T90189-05142 GROMMET, SCREW			2.00	2.40		4.80
2	2	S53114-0D020 GRILLE, RADIATOR02			1.00	254.50		254.50
3	3	S81430-0D060 LAMP ASSY, DAYTIME			1.00	691.60		691.60
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle 		Parts		950.90	GST 7.00%	
				Labour		0.00		
				Sublet		0.00	Less	
				Lubrication/Fluid		0.00		
				Others		0.00		
				Amount Due		1,017.46		

Company Copy