



Borneo Motors

incheape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no. : 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Yong Pui Chong				
		Document No. 0	10D Braddell Hill #10-13 Singapore 579723				
		Document Date 10/03/2022	Mobile: 91997153				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	01/03/2022 15.07	10/03/2022 18.00	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SMC3498H ACC DATE:28/02/2022 TP INS:INDIA NO.OF REPAIR DAYS:12 DATE-IN:28/02/2022 DATE SURVEY:01/03/2022 BY:LKK-MARCUS AUTHORISED ON:04/03/2022 -TP/DS CLAIM				30.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR BONNET				60.00	
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.	BP02			122.40	
5	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	BP02			2160.00	
6	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	*			1770.00	
7	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR BOOTLID AND REAR END PANEL.				120.00	
8	B	BP-LAB2 TO CONDUCT WATER LEAK TEST.	BP02			122.40	
9	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS.	BP02			180.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet		Amount Due		
			Lubrication/Fluid				
			Others				

Company Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA


ESTIMATE

Account Details		Account No. S1000006 / ICIII1		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		Document No. 0		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153			
		Document Date 10/03/2022					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3701191537	2NR5399835	60	Raymond Seah L M	01/03/2022 15.07	10/03/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB2 R/I REAR CARPET,TRIMMING AND OTHER ATTACHMENT TO FACILITATE REPAIRS.	BP02			360.00
11	B	BP-LAB2 TO TRANSFER REAR BOOTLID MECHANISM AND COMPONENT TO NEW PANELS.	BP02			360.00
12	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS	BP02			2880.00
13	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	*			2360.00
14	1	S81110-0DF50 HEADLAMP ASSY,RH G	1.00	1668.80		1668.80
15	2	S81150-0DF50 HEADLAMP ASSY,LH G	1.00	1668.80		1668.80
16	3	S53112-0D650 GRILLE, RADIATOR, LW	1.00	387.30		387.30
17	4	S53113-0D020 GRILLE,RADIATOR22	1.00	96.60		96.60
18	5	S52119-0U932 COVER, FR BUMPER02	1.00	525.80		525.80
19	6	S52161-0K040 PIECE, RR BUMPER	4.00	4.30		17.20
20	7	S52535-0D230 RETAINER, FR BUMPER02	1.00	106.70		106.70
21	8	S52536-0D230 RETAINER, FR BUMPER22	1.00	106.70		106.70
22	9	T90467-05170 CLIP	2.00	2.70		5.40
23	0	T47749-33030 CLIP, PIN HOLD	2.00	9.20		18.40
24	1	T53879-33030 RETAINER, FR FENDER	1.00	12.80		12.80
25	2	S53111-0D912 GRILLE, RADIATOR22	1.00	75.40		75.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Company Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153					
		Document No. 0						
		Document Date 10/03/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	01/03/2022	15.07	10/03/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
26	3	S53123-0D050	MOULDING, RADIATOR G			1.00	73.40	73.40
27	4	S53124-0D040	MOULDING, RADIATOR G			1.00	73.40	73.40
28	5	S90975-T2008	EMBLEM,SYMBOL22			1.00	61.90	61.90
29	6	S53301-0D280	HOOD SUB-ASSY22			1.00	982.10	982.10
30	7	U90467-07217	CLIP			10.00	2.70	27.00
31	8	SPC507-0D015 43	BACK SENSOR 218 ATTITUDE BLACK			1.00	198.50	198.50
32	9	S52562-0D130	RETAINER, RR BUMPER,			1.00	63.40	63.40
33	0	S52563-0D130	RETAINER, RR BUMPER,			1.00	63.40	63.40
34	1	S81910-0D050	REFLECTOR ASSY22			1.00	99.80	99.80
35	2	S52159-0U963	COVER, RR BUMPER22			1.00	557.70	557.70
36	3	S75895-0D270	TAPE, MOULDING, NO.1			2.00	53.50	107.00
37	4	S52161-0K040	PIECE, RR BUMPER			4.00	4.30	17.20
38	5	S52575-0D340	RETAINER, RR BUMPER22			1.00	164.30	164.30
39	6	S52576-0D330	RETAINER, RR BUMPER02			1.00	164.30	164.30
40	7	S52023-0D090	REINFORCEMENT,RR02			1.00	353.10	353.10
41	8	S58307-0D480	PANEL,LAMP LOWER02			1.00	786.30	786.30
42	9	S58387-0D200	PLATE, RR FLOOR22			1.00	295.40	295.40
43	0	T90467-08186 C3	CLIP			2.00	2.60	5.20
44	1	S64401-0D360	PANEL,LUGGAGE DR02			1.00	838.90	838.90
45	2	S64461-0D180	WEATHERSTRIP22			1.00	186.50	186.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Company Copy



Borneo Motors

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No. S1000006 / ICIII1		Customer Details				
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		Document No. 0		Mr Yong Pui Chong 10D Braddell Hill #10-13 Singapore 579723 Mobile: 91997153				
		Document Date 10/03/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	17/07/2020	SMT7760J	0	21638	69DS/SMT7760J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3701191537		2NR5399835	60	Raymond Seah L M	01/03/2022 15.07		10/03/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
46	3	S64600-0D040 LOCK ASSY, LUGG C 22			1.00	423.90		423.90
47	4	S75431-02090 EMBLEM,LUGGAGE22			1.00	65.30		65.30
48	5	S75442-0D400 PLATE, LUGGAGE02			1.00	48.30		48.30
49	6	S75444-0D700 PLATE, LUGGAGE COMPT			1.00	37.60		37.60
50	7	T53119-12150 FRT GRILLE CUSHION,			2.00	20.90		41.80
51	8	S53208-0D901 SUPPORT SUB-ASSY, HO			1.00	159.30		159.30
52	9	T90189-05142 GROMMET,SCREW			2.00	2.40		4.80
53	0	S53114-0D020 GRILLE, RADIATOR02			1.00	254.50		254.50
54	1	S81430-0D060 LAMP ASSY, DAYTIME			1.00	691.60		691.60
55	2	S81560-0DA41 LAMP ASSY, RR			1.00	676.20		676.20
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 22,916.80		
		Please acknowledge receipt of vehicle		Parts	12,212.00	GST 7.00%	1,604.18	
				Labour	10,524.80	Less	0.00	
				Sublet	180.00			
				Lubrication/Fluid	0.00			
				Others	0.00			
						Amount Due	24,520.98	

Company Copy