

ESTIMATE OF REPAIR

Veh# : YP9221P

Model:

MIT FUSO

Accident Date : 1/3/2022

24/7/2018

Location : FARRER FLYOVER TOWARDS THOMSON

3P:

GBD1560Z (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear o/s pillar <i>h/r</i>		800.00	x
2	1 pc	O/s box rear door panel <i>Bent</i>		1,500.00	1400.
3	3pcs	O/s box rear door panel hinges <i>new</i>		300.00	x
4	1pc	O/s box rear door panel lock middle <i>Best</i>		250.00	✓
5	1pc	O/s box rear door panel sticker <i>new new</i>		150.00	✓
6	1 pc	N/s box rear door panel <i>new</i>		1,500.00	x
7	3pcs	N/s box rear door panel hinges <i>3pc new</i>		300.00	x
8	1pc	N/s box rear door panel lock middle		250.00	x
9	1pc	N/s box rear door panel sticker <i>new</i>		150.00	x
10	1 pc	Rear tail-gate lower wooden cross member <i>cracked</i>		500.00	450
11	2pcs	Rear o/s & n/s stopper <i>o/s cut</i>		180.00	90
12	1 pc	Rear step <i>cracked</i>		150.00	✓
13	2 pcs	Rear step bolt <i>Best</i>		100.00	50.
14	2 pcs	Rear o/s & n/s long wooden member <i>o/s cracked</i>		1,400.00	600
15	8pcs	Rear o/s & n/s wooden member U-bolt <i>3 pieces Best</i>		800.00	300.
16	2pcs	Rear o/s & n/s tail-lamp bracket <i>o/s Best</i>	250.00	130.20	
17	2pcs	Rear o/s & n/s tail-lamp <i>o/s cracked</i>	610.00	305	
18	60pcs	Rivets <i>new</i>		60.00	40.
19	1 pc	Rear reg. no. plate <i>new</i>		45.00	x
20	1 pc	Rear LTA rear guard <i>Best</i>		1,800.00	800
21	1 pc	Rear LTA rear guard step <i>Best</i>		500.00	350
		Sub-Total:	870.40	10,735.00	0.00
			25%	0%	0%
		After Less %:	652.80	10,735.00	0.00
		Labour			
1		To repair front cabin panel dismantle, straighten and welding damage parts		1,800.00	7400
2		To spray painting		500.00	400.
3		To remove and refit rear carriage to facilitate changing wooden cross member		300.00	x
4		Provide lifting equipment to remove rear carriage)		800.00	500
5		To check wiring		120.00	30
6		To re-seal anti-rust		120.00	50.
		Sub-Total:		3,640.00	
		Total:		15,027.80	
		After Less 20%:		12,022.24	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

24 hr accident call
Acknowledged by Repairer

Signature: YP9221P ESTIMATEPg1

Date:

Supplementary: 2050
Total: 8196.40
L/S: 6.5K.



2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : YP9221P

Model:

MIT FUSO

Accident Date : 1/3/2022

24/7/2018

Location : FARRER FLYOVER TOWARDS THOMSON

3P:

GBD1560Z (AIG)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	O/s panel <i>ply</i>		3,400.00	X
2	1 pc	O/s panel sticker <i>new</i>		800.00	550
3	8pcs	Rear carriage floor planks (14ft Chengal) <i>3 pieces included</i>		3,200.00	900
4	6 pcs	Rear horizontal cross member (short) <i>3 pieces included</i>		1,500.00	600
5	1 pc	Rear n/s long wooden member (refer to pg 1 No 14)			
		Sub-Total:	0.00	8,900.00	0.00
			25%	0%	0%
		After Less %:	0.00	8,900.00	0.00
		Total:		8,900.00	
		After Less 20%:		7,120.00	

Chan

Chan San Choon

Director

DipEng, AAE MIMI,MSAE(Aust)

Supplementary: 2020

