



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 2338U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	SCRATCHED	2,850.00	1,405.95
1	FRONT BUMPER LOWER GRILLE	SCRATCHED	450.00	69.15
1	FRONT GRILLE CHROME RH	SCRATCHED	280.00	146.40
1	FRONT GRILLE RH	NOT NECESSARY	290.00	-
1	FRONT HEADLAMP LED RH	CRACKED	7,320.00	4,887.60
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	330.00	-
	LESS 5% DISCOUNT		-576.00	-325.46
			10,944.00	6,183.64
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	SCRATCHED	45.00	35.00
1	FRONT BUMPER CLIPS (SN)	NECESSARY	45.00	30.00
			90.00	65.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REFIT FRONT BUMPER SENSOR.		80.00	60.00
	TO COMPUTER RESET AND RE-PROGRAMME ALL FAULT CODE.		350.00	100.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		800.00	300.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	70.00	-
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		350.00	250.00
			1,680.00	740.00
	GRAND TOTAL		12,714.00	6,988.64

Report Ref No. CS/FCI22001931/Rvy3e2



RECOMMENDED COST OF REPAIRS			6,988.64
-----------------------------	--	--	----------

Report Ref No. CS/FCI22001931/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.