

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>sub</i>	2,850.00 1405.95	-5.00	2,707.50 1335.65
2	1	FRONT BUMPER LOWER GRILLE <i>? sub</i>	450.00 69.15	-5.00	427.50 65.69
3	1	FRONT GRILLE CHROME RH <i>sub</i>	280.00 46.40	-5.00	266.00 43.98
4	1	FRONT GRILLE RH <i>? fan</i>	290.00 290.00	-5.00	275.50 275.50
5	1	FRONT HEADLAMP LED RH <i>? can</i>	7,320.00 421.60	-5.00	6,954.00 400.52
6	1	FRONT HEADLAMP LOWER BRACKET RH <i>? fan</i>	330.00 330.00	-5.00	313.50 313.50
Total Parts (\$\$)					10,944.00 <i>6183.64</i>

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE <i>sub</i>	45.00	0.00	45.00 <i>35</i>
2	1	FRONT BUMPER CLIPS <i>sub</i>	45.00	0.00	45.00 <i>30</i>
Sub Total (\$\$)					90.00 <i>65</i>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 <i>✓</i>
2	1	To Remove and Refit Front Bumper Sensor.	80.00	0.00	80.00 <i>60</i>
3	1	To Computer Reset and Re-program all fault code.	350.00	0.00	350.00 <i>100</i>
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00 <i>300</i>
Gross Labour Cost (\$\$)					1,260.00 <i>490</i>

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	70.00	0.00	70.00 <i>X nn</i>
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	350.00	0.00	350.00 <i>250</i>
Gross Labour Cost (\$\$)					420.00 <i>250</i>

Gross Labour Cost (\$\$) 420.00

< END OF ESTIMATES >

Rasul
Hp 90010068
3 days
P/P
02/03/21 @ 1100
Resury before paint

6183.64

65.00

490.00

250.00

6988.64