

ASS. REC. BY: TauhinREF: CC4/LPC 22001932/TE93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 4480R Yr Regn: 2016, March
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yutong ZK6930M C.C. 6620Colour: Black A/C: Insured / Std / NI / NASp. Reading: 29/9/13 T/Radio: Insured / Std / NI / NAEng/No: L2YTCID68F1024788

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim orTyre Size: F: 275/70R22-5
R: 1 - (D)BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. P mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 8/8 mmL/Bal. 8/8 mmD.O.I. 4/3/21 Pro30Think one Autocane.Frt N/S

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B. / F

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Think One Autocare Pte Ltd
No:60 Jalan Lam Huat #02-32 Carros Centre
Singapore 737869

ESIMATED

PC4480R YUTONG ZK6930H

DATE 3.5.2021

AMOUNT S\$

No	Qty	PARTICULAR		AMOUNT S\$
1	1	FRONT REAR VIEW MIRROR ASSY LH		\$ 1,420.00 <i>brw</i>
2	1	BRACKET MIRROR C/W BOLT		\$ 165.00 <i>brw</i>
				\$ 1,585.00
			LESS 10%	\$ 158.50
				\$ 1,426.50

LABOUR & MISCELLANEOUS:

1	To remove/replace rear view mirror arm with all necessary attachment	250.00 <i>200</i>
2	To spray paint replaced parts inclusive of preparatory works and painting materials	200.00 <i>150</i>
		<u>\$ 1,876.50</u>

Taufik 97495749
WP/ 4/3/22 @ 1030
1 day
taufik@lkhauto.com
** To check for price*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: