



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI22001935/y3 Date: 01/03/2022 Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMM 7507L	Veh. Inspected	SMP 2948P
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNM22D201457/C02/SMM7507 L/CHNGPW	Excess (\$)	0.00
	Assign From	ADELINE CHNG	Assign Date	01/03/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	26/02/2022	Inspection Date	
	Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			