

ASS. REC. BY:

REF:

105 / CS/ICS22001936/Kqy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

DMPC2200082H/CT

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

01/31

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Smx 837Y

Yr Regn:

01, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

c.c

2497

Colour

Mett Black

A/C: Insured / Std / NI / NA

Sp. Reading

140757

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP32050C 547684

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/2/22

D.O.I.

2/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/03/22 @ 10.35am revert to Crystabelle via Merimen.

04/03/22 @ 2.01pm Crystabelle Tan informed C/A at LS \$19500 via Merimen.

07/03/22 @ 4.55pm Informed Dorlyn C/A not more than LS \$19500 & ex: \$3750 by email.

Kenneth finalised LS \$25000, 14 days. (Red \$12870.50, 34%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 01/06 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ + RS. \$


) Firms

) Others

Report Format: MER-OD

Lump Sum H.B.T. (\$) 25000

TOTAL



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MPC22A00011700	Date of Loss:	24/02/2022
Vehicle Reg. No.:	SMX837Y	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM PEI XIAN		
Driver:	LIM JIA ANN EUGENE		

Make/Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Vehicle Reg. Date:	20/01/2011
Vehicle Colour:	BLACK	Chassis No:	WBAFP32050C547684
Engine No:	02557649N52B25AF		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0 <i>14 days</i>

*Not Authorized
L1Rm &
Repair After Paint
Ex @ 3750/-*

Description of Accident/Loss: REFER TO GIA REPORT

Remarks: OWNER ARRANGE TOW INTO ANG MO KIO WORKSHOP ON 24/02/2022 @ AFTERNOON

Present Location: CHENG HOE MOTOR PTE LTD (AMK)

COST OF CLAIMS

	Amount
Parts	33,308.00
Miscellaneous Items	70.00
Labour	3,310.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	36,688.00
- Excess (S\$)	3,750.00
(S\$)	32,938.00
+ GST 7.00% (S\$)	2,305.66
Nett Amount (S\$)	35,243.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: DORLYN LI YAZHU

DETAILS

Reference

Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2022)
Parts:	143	BMW 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper <i>BT ✓</i>	0.00	0.00	*1,450.00 F
2	1		*1 pc front bumper reinforcement <i>BT ✓</i>	0.00	0.00	*530.00 F
3	1		*1 pc front bumper sponge <i>CM ✓</i>	0.00	0.00	*70.00 F
4	1		*1 pc front bumper logo <i>DU ✓</i>	0.00	0.00	*75.00 F
5	1		*1 pc front bumper lower reinforcement <i>?</i>	0.00	0.00	*180.00 F
6	1		*2 pcs front bumper fog lamps @ \$210/pc <i>O/S COR LX NIS ?</i>	0.00	0.00	*420.00 F
7	1		*1 pc front bumper lower centre grille <i>CM ✓</i>	0.00	0.00	*80.00 F
8	1		*2 pcs front bumper lower side grilles @ \$80/pc <i>NIS ✓</i>	0.00	0.00	*160.00 F
9	1		*2 pcs front bumper lower side grille trims @ \$40/pc <i>NIS ✓</i>	0.00	0.00	*80.00 F
10	1		*4 pcs front bumper parking sensors @ \$170/pc <i>T ✓</i>	0.00	0.00	*680.00 F
11	1		*1 set front bumper parking sensor wire harness <i>?</i>	0.00	0.00	*160.00 F
12	1		*2 pcs front grilles @ \$120/pc <i>DU ✓</i>	0.00	0.00	*240.00 F
13	1		*1 pc bonnet <i>BU ✓</i>	0.00	0.00	*1,960.00 F
14	1		*2 pcs bonnet gas struts @ \$120/pc <i>BU ✓</i>	0.00	0.00	*240.00 F
15	1		*2 pcs bonnet hinges @ \$90/pc <i>DU ✓</i>	0.00	0.00	*180.00 F
16	1		*2 pcs bonnet upper locks @ \$70/pc <i>BT ✓</i>	0.00	0.00	*140.00 F
17	1		*2 pcs bonnet lower inner locks @ \$170/pc <i>BT ✓</i>	0.00	0.00	*340.00 F
18	1		*1 pc bonnet seal <i>BT ✓</i>	0.00	0.00	*40.00 F
19	1		*2 pcs front fenders @ \$930/pc <i>BU ✓</i>	0.00	0.00	*1,860.00 F
20	1		*2 pcs front fender side panel brackets @ \$50/pc <i>O/S BT LX NIS ?</i>	0.00	0.00	*100.00 F
21	1		*2 pcs front fender inner shields (Front) @ \$140/pc <i>O/S CM LX</i>	0.00	0.00	*280.00 F
22	1		*2 pcs front fender side covers @ \$250/pc <i>CM ✓</i>	0.00	0.00	*500.00 F
23	1		*1 pc air filter housing assy <i>CM ✓</i>	0.00	0.00	*460.00 F
24	1		*2 pcs front wheel house @ \$2300/pc <i>O/S BT NIS ? LX</i>	0.00	0.00	*4,600.00 F
25	1		*1 pc front top panel <i>BT ✓</i>	0.00	0.00	*180.00 F
26	1		*1 pc front top panel inner top garnish <i>CM ✓</i>	0.00	0.00	*360.00 F
27	1		*1 pc front top panel inner <i>BT ✓</i>	0.00	0.00	*150.00 F
28	1		*2 pcs front top panel side support @ \$40/pc <i>BT ✓</i>	0.00	0.00	*80.00 F
29	1		*2 pcs front cross brace panel @ \$40/pc <i>BT ✓</i>	0.00	0.00	*80.00 F
30	1		*2 pcs headlamps @ \$1500/pc <i>BU ✓</i>	0.00	0.00	*3,000.00 F
31	1		*2 pcs headlamp ballast module @ \$850/pc <i>?</i>	0.00	0.00	*1,700.00 F
32	1		*2 pcs headlamp nozzle assy @ \$145/pc <i>BU ✓</i>	0.00	0.00	*290.00 F
33	1		*2 pcs headlamp panels @ \$230/pc <i>BT ✓</i>	0.00	0.00	*460.00 F
34	1		*1 unit headlamp nozzle water hose <i>?</i>	0.00	0.00	*60.00 F
35	1		*1 pc air-con condenser <i>BT ✓</i>	0.00	0.00	*720.00 F
36	1		*1 pc air-con condenser suction hose <i>DU ✓</i>	0.00	0.00	*230.00 F
37	1		*1 pc air-con condenser discharge hose <i>DU ✓</i>	0.00	0.00	*240.00 F
38	1		*1 pc air-con condenser liquid pipe <i>DU ✓</i>	0.00	0.00	*200.00 F
39	1		*1 pc air-con compressor <i>?</i>	0.00	0.00	*2,600.00 F
40	1		*1 pc radiator <i>BT ✓</i>	0.00	0.00	*600.00 F
41	1		*1 pc radiator top cowling <i>CM ✓</i>	0.00	0.00	*50.00 F

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Part No.	Particulars	%Disc	%Depr	Amount
	*1 pc radiator bottom cowling ?	0.00	0.00	*160.00 F
	*1 pc radiator fan motor assy <i>Tm</i>	0.00	0.00	*810.00 F
	*1 pc radiator top hose <i>Pur</i>	0.00	0.00	*85.00 F
	*1 pc radiator bottom hose ?	0.00	0.00	*140.00 F
46	*1 pc radiator heat exchanger ?	0.00	0.00	*450.00 F
47	*1 pc radiator spare tank <i>CPA</i>	0.00	0.00	*140.00 F
48	*1 pc power steering cooler <i>Rm</i> ?	0.00	0.00	*310.00 F
49	*1 pc oil filter housing heat exchanger <i>Rt</i>	0.00	0.00	*230.00 F
50	*1 pc oil filter o ring <i>mm</i>	0.00	0.00	*40.00 F
51	*1 pc water pump ?	0.00	0.00	*580.00 F
52	*1 pc fan belt ?	0.00	0.00	*60.00 F
53	*1 pc fan belt tensioner ?	0.00	0.00	*150.00 F
54	*1 pc alternator ?	0.00	0.00	*1,300.00 F

F=Franchise part.

Sub Total (\$)	30,280.00
+ Margin on L,N Items 10.00% (\$)	3,028.00
Total Parts (\$)	33,308.00

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 pc front number plate <i>✓ CPA</i>	35.00
2	1	1 unit coolant <i>✓ mm</i>	35.00
Sub Total (\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Towing (arrange by owner) paid by owner - invoice with owner	New	150.00 <i>✓</i>
2	Remove & refix air-con condenser,check,vacuum & refill gas	New	100.00 <i>✓</i>
3	Remove & refix front bumper & attachments,grilles,bonnet & attachments,both fenders,frt support panel;to cut,weld & renew both front wheel housings;knocking & repair frt chassis frames & realign the same	New	1100 1,200.00
4	Putty & respray frt bumper,parking sensors,bonnet,both frt fenders,both wheel housings & all affected areas	New	950 1,000.00
5	Remove & refix parking sensors,wire harness & reset the same	New	80.00 <i>✓</i>
6	Remove & refix engine & gearbox assy,both undercarriage & realign the same	New	? 500.00
7	To conduct computer wheel alignment	New	80 80.00
8	To reset & reprogramme headlamp modules	New	150 200.00
Gross Labour Cost (\$)			3,310.00

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	069E
Vehicle Details	
Vehicle No.:	SMX837Y
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Feb 2022
Vehicle Make:	B.M.W.
Vehicle Model:	523i 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	02557649N52B25AF
Chassis No.:	WBAFP32050C547684
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$37,471.00
Original Registration Date:	20 Jan 2011
First Registration Date:	20 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$37,471.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2031
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$42,683.00
COE Rebate Amount:	\$38,001.00
Total Rebate Amount:	\$38,001.00

The information contained herein is correct as at 24 Feb 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/02/2022 17:23 (SGT)
Date of Accident 24/02/2022 08:56 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE TOWARDS CHANGI
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMX837Y

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM PEI XIAN
NRIC No SXXXX069E
Email Address peixian_0417@hotmail.com
Mobile Phone No (Phone) +65-96620473
Alternative Phone No +65-96620473

VEHICLE PARTICULARS

Manufacturer BMW
Model 523i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 2500

INSURANCE COMPANY

Name of Insurance Company ECICS Limited
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MPC22A00011700
Cover Note Number 09/02/2022 - 08/02/2023

DRIVER

Name of Driver LIM JIA ANN EUGENE
NRIC No SXXXX553F

A 3D coordinate system with axes labeled x , y , and z . The x -axis is horizontal, the y -axis is vertical, and the z -axis is diagonal. A point is marked at the intersection of the axes.

A. Smx 837Y
(alone)

B. SLQ9197
(alone)

C. SLZ98229
(alone)

Vehicle No: SMX837Y (ECICS)
Date & Time: 24/02/2022 @ 0856 (raining / wet)

Motor car SLA919T e-brake in front, as such i follow too but couldn't in time and thus hit onto the back of SLA919T. Upon alighting, i realised there was another car SLZ9822G in front of SLA919T, involved in the accident as well. I was involved in a 3 car chain collision with no one injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/FIN No.:

- ☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()