

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 23 Mar 2022

**Preliminary Advice**

|                    |                                                                                                          |                         |                  |
|--------------------|----------------------------------------------------------------------------------------------------------|-------------------------|------------------|
| Vehicle No         | : SMX837Y                                                                                                | Accident Date           | : 24/02/2022     |
| Make               | : BMW 523i                                                                                               | Policy No.              | : MPC22A00011700 |
| Assignment Date    | : 01/03/2022                                                                                             | Excess                  | : S\$3,750.00    |
| Date of Inspection | : 02/03/2022                                                                                             | Est. Duration of Repair | : 14             |
| Inspection At      | : CHENG HOE MOTOR PTE LTD (YISHUN)<br>BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A<br>SINGAPORE 768761 |                         |                  |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |                |
|-----------------------------|----------------|
| Repairer's Estimate (Gross) | :S\$ 37,870.50 |
| Revised Amount              | :S\$ 25,545.50 |
| Check Items (Estimated)     | :S\$ 12,105.00 |
| Total                       | :S\$ 37,650.50 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

**Total Loss Consideration**

|                    |                |
|--------------------|----------------|
| New for Old Value  | :S\$           |
| Pre-Accident Value | :S\$ 90,000.00 |
| COE / PARF Rebate  | :S\$ 38,001.00 |
| Salvage Value      | :S\$           |

Margin for Repair

:S\$ 51,999.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.