

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 03 Mar 2022

Preliminary Advice

Vehicle No	: SMX837Y	Accident Date	: 24/02/2022
Make	: BMW 523i	Policy No.	: MPC22A00011700
Assignment Date	: 01/03/2022	Excess	: S\$3,750.00
Date of Inspection	: 02/03/2022	Est. Duration of Repair	: 14
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 36,688.00
Revised Amount	:S\$ 24,363.00
Check Items (Estimated)	:S\$ 12,105.00
Total	:S\$ 36,468.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 90,000.00
COE / PARF Rebate	:S\$ 38,001.00
Salvage Value	:S\$

Margin for Repair

:S\$ 51,999.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.