

Shiau Chan (LKKAUTO)

From: Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>
Sent: Monday, 28 March 2022 12:08 PM
To: Shiau Chan (LKKAUTO); Cheng Hoe
Subject: Re: FW: ECICS-OD SMX 837Y DOA: 24/02/2022

Hi Shiau Chan,

As per estimate & supplementary till date (28/03/2022), we agreed on repair cost not more than Lump sum S\$25,000/- (excluding further supplementary).

Thank you.

Rgds
Dorlyn Li
Cheng Hoe Motor Pte Ltd (AMK)
Tel: 64812001

On Mon Mar 07 2022 16:55:14 GMT+0800 (Singapore Standard Time) Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

----- Original Message -----

Dear Dorlyn,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **SMX 837Y at repair cost not more than Lump Sum \$19,500/- or whichever lower** (Excess \$3,750/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,
Shiau Chan (Ms)
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com
| fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)