



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ECICS
Policy No:	MPC22A00011700	Date of Loss:	24/02/2022
Vehicle Reg. No.:	SMX837Y	Driveable?	
Driver Age/Info:	24 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM PEI XIAN		
Driver:	LIM JIA ANN EUGENE		
Make/Model:	BMW 523i, 2.5 AT ABS D/AB 2WD	Vehicle Reg. Date:	20/01/2011
Vehicle Colour:	4DR GAS/D NAV (A)		
Engine No:	BLACK	Chassis No:	WBAFP32050C547684
Odometer:	02557649N52B25AF		
	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0 14 days		
Description of Accident/Loss	REFER TO GIA REPORT		
Remarks:	OWNER ARRANGE TOW INTO ANG MO KIO WORKSHOP ON 24/02/2022 @ AFTERNOON		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

NOT Withheld
11 Pm @ 25,000k
Repair After Paint
Ex @ 3750k

COST OF CLAIMS

	Amount
Parts	33,308.00
Miscellaneous Items	70.00
Labour	3,310.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	36,688.00
- Excess (\$\$)	3,750.00
(\$\$)	32,938.00
+ GST 7.00% (\$\$)	2,305.66
Nett Amount (\$\$)	35,243.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

is claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Sum / I.B.I: (\$

Tech Invs (\$

Weekend (\$

TOTAL

EPAIR DETAILS

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Mar 2022)
 143 BMW 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
 Code: Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05
 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page
 Other Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Qty	Part No.	Particulars	%Disc	%Depr	Amount
1		*1 pc front bumper <i>BT ✓</i>	0.00	0.00	*1,450.00 F
1		*1 pc front bumper reinforcement <i>BT ✓</i>	0.00	0.00	*530.00 F
1		*1 pc front bumper sponge <i>CM ✓</i>	0.00	0.00	*70.00 F
1		*1 pc front bumper logo <i>BT ✓</i>	0.00	0.00	*75.00 F
1		*1 pc front bumper lower reinforcement <i>BT ✓</i>	0.00	0.00	*180.00 F
2		*2 pcs front bumper fog lamps @ \$210/pc <i>BT CM LT NIS MY CM ✓</i>	0.00	0.00	*420.00 F
1		*1 pc front bumper lower centre grille <i>CM ✓</i>	0.00	0.00	*80.00 F
2		*2 pcs front bumper lower side grilles @ \$80/pc <i>BT ✓</i>	0.00	0.00	*160.00 F
2		*2 pcs front bumper lower side grille trims @ \$40/pc <i>BT ✓</i>	0.00	0.00	*80.00 F
4		*4 pcs front bumper parking sensors @ \$170/pc <i>BT ✓</i>	0.00	0.00	*680.00 F
1		*1 set front bumper parking sensor wire harness <i>BT ✓</i>	0.00	0.00	*160.00 F
2		*2 pcs front grilles @ \$120/pc <i>BT ✓</i>	0.00	0.00	*240.00 F
1		*1 pc bonnet <i>BT ✓</i>	0.00	0.00	*1,960.00 F
2		*2 pcs bonnet gas struts @ \$120/pc <i>BT ✓</i>	0.00	0.00	*240.00 F
2		*2 pcs bonnet hinges @ \$90/pc <i>BT ✓</i>	0.00	0.00	*180.00 F
2		*2 pcs bonnet upper locks @ \$70/pc <i>BT ✓</i>	0.00	0.00	*140.00 F
2		*2 pcs bonnet lower inner locks @ \$170/pc <i>BT ✓</i>	0.00	0.00	*340.00 F
1		*1 pc bonnet seal <i>BT ✓</i>	0.00	0.00	*40.00 F
2		*2 pcs front fenders @ \$930/pc <i>BT ✓</i>	0.00	0.00	*1,860.00 F
2		*2 pcs front fender side panel brackets @ \$50/pc <i>BT CM LT NIS R ✓</i>	0.00	0.00	*100.00 F
2		*2 pcs front fender inner shields (Front) @ \$140/pc <i>BT CM LT ✓</i>	0.00	0.00	*280.00 F
2		*2 pcs front fender side covers @ \$250/pc <i>BT ✓</i>	0.00	0.00	*500.00 F
1		*1 pc air filter housing assy <i>CM ✓</i>	0.00	0.00	*460.00 F
2		*2 pcs front wheel house @ \$2300/pc <i>BT CM LT NIS R LT ✓</i>	0.00	0.00	*4,600.00 F
1		*1 pc front top panel <i>BT ✓</i>	0.00	0.00	*180.00 F
1		*1 pc front top panel inner top garnish <i>CM ✓</i>	0.00	0.00	*360.00 F
1		*1 pc front top panel inner <i>BT ✓</i>	0.00	0.00	*150.00 F
2		*2 pcs front top panel side support @ \$40/pc <i>BT ✓</i>	0.00	0.00	*80.00 F
2		*2 pcs front cross brace panel @ \$40/pc <i>BT ✓</i>	0.00	0.00	*80.00 F
2		*2 pcs headlamps @ \$1500/pc <i>BT ✓</i>	0.00	0.00	*3,000.00 F
2		*2 pcs headlamp ballast module @ \$850/pc <i>BT ✓</i>	0.00	0.00	*1,700.00 F
2		*2 pcs headlamp nozzle assy @ \$145/pc <i>BT ✓</i>	0.00	0.00	*290.00 F
2		*2 pcs headlamp panels @ \$230/pc <i>BT ✓</i>	0.00	0.00	*460.00 F
1		*1 unit headlamp nozzle water hose <i>BT ✓</i>	0.00	0.00	*60.00 F
1		*1 pc air-con condenser <i>BT ✓</i>	0.00	0.00	*720.00 F
1		*1 pc air-con condenser suction hose <i>BT ✓</i>	0.00	0.00	*230.00 F
1		*1 pc air-con condenser discharge hose <i>BT ✓</i>	0.00	0.00	*240.00 F
1		*1 pc air-con condenser liquid pipe <i>BT ✓</i>	0.00	0.00	*200.00 F
1		*1 pc air-con compressor <i>BT ✓</i>	0.00	0.00	*2,600.00 F
1		*1 pc radiator <i>BT ✓</i>	0.00	0.00	*600.00 F
1		*1 pc radiator top cowling <i>CM ✓</i>	0.00	0.00	*50.00 F

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	1				
43	1	*1 pc radiator bottom cowling			
44	1	*1 pc radiator fan motor assy			
45	1	*1 pc radiator top hose	0.00	0.00	*160.00 F
46	1	*1 pc radiator bottom hose	0.00	0.00	*810.00 F
47	1	*1 pc radiator heat exchanger	0.00	0.00	*85.00 F
48	1	*1 pc radiator spare tank	0.00	0.00	*140.00 F
49	1	*1 pc power steering cooler	0.00	0.00	*450.00 F
50	1	*1 pc oil filter housing heat exchanger	0.00	0.00	*140.00 F
51	1	*1 pc oil filter o ring	0.00	0.00	*310.00 F
52	1	*1 pc water pump	0.00	0.00	*230.00 F
53	1	*1 pc fan belt	0.00	0.00	*40.00 F
54	1	*1 pc fan belt tensioner	0.00	0.00	*580.00 F
		*1 pc alternator	0.00	0.00	*60.00 F
			0.00	0.00	*150.00 F
			0.00	0.00	*1,300.00 F
Sub Total (\$\$)					30,280.00
+ Margin on L,N Items 10.00% (\$\$)					3,028.00
Total Parts (\$\$)					33,308.00

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc front number plate	✓ CM 35.00
2	1	1 unit coolant	✓ MC 35.00
Sub Total (\$\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Towing (arrange by owner) paid by owner - invoice with owner	New	✓ 150.00
2	Remove & refix air-con condenser,check,vacuum & refill gas	New	✓ 100.00
3	Remove & refix front bumper & attachments,grilles,bonnet & attachments,both fenders,frt support panel;to cut,weld & renew both front wheel housings;knocking & repair frt chassis frames & realign the same	New	1100/ 1,200.00
4	Putty & respray frt bumper,parking sensors,bonnet,both frt fenders,both wheel housings & all affected areas	New	950/ 1,000.00
5	Remove & refix parking sensors,wire harness & reset the same	New	✓ 80.00
6	Remove & refix engine & gearbox assy,both undercarriage & realign the same	New	NN X 500.00
7	To conduct computer wheel alignment	New	60/ 80.00
8	To reset & reprogramme headlamp modules	New	150/ 200.00
Gross Labour Cost (\$\$)			3,310.00

Cheng Hoe Motor Pte Ltd/SMX837Y/01/03/2022 14:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >