

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22001938/TNY3E2**Date:** 12/10/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SJG9931Z **Insured Vehicle No :** SLK5116S

Date of Loss: 26/02/2022 Nature of Claim: TP Claim No: MFL2022D0001078

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG9931Z**

Make & Model: HONDA CIVIC, 1.6 (A) Engine No: R16A13005340

Reg. Date: 23/07/2008 (Man. Year: 2008) Chassis No: JHMFD45208S201732

Colour: Black Odometer: 192181 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Windforce 6 mm Rear Left Side: Windforce 6 mm

Front Right Side: Windforce 6 mm Rear Right Side: Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,980.80	7,520.50	6,460.30	46.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,880.00	2,340.00	3,540.00	60.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,860.80	9,860.50	10,000.30	50.35
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	19,860.80	7,900.00	11,960.80	60.22
+ GST 7.00/7.00% (S\$)	1,390.26	553.00	837.26	60.22
Nett Amount (S\$)	21,251.06	8,453.00	12,798.06	60.22

INSPECTION

Date of Assignment: 01/03/2022

Date Inspected: 02/03/2022 Inspected At:

1 Kaki Bukit Avenue 6 #01-08 Autobay@Kaki Bukit
Repairer: TSL Auto Garage

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Oct 2022)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG9931Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER	Not Necessary	598.00 FL	*- FL
2	1		*RH FRONT FENDER LAMP	Not Necessary	68.00 FL	*- FL
3	1		*RH FRONT DOOR	Bent	894.00 FL	*894.00 FL
4	1		*RH FRONT DOOR MIRROR	Distorted	582.00 FL	*582.00 FL
5	1		*RH FRONT DOOR OUTER HANDLER	Distorted	145.00 FL	*145.00 FL
6	1		*RH FRONT DOOR OUTER HANDLER CHROME	Cut	85.00 FL	*85.00 FL
7	1		*RH FRONT DOOR PROTECTOR	Cut	163.00 FL	*163.00 FL
8	1		*RH FRONT DOOR PROTECTOR CHROME	Cut	126.00 FL	*126.00 FL
9	1		*RH FRONT DOOR LOCK	Cracked	283.00 FL	*283.00 FL
10	1		*RH FRONT DOOR LOCK CATCH	Not Necessary	32.00 FL	*- FL
11	2		*RH FRONT DOOR HINGE	Not Necessary	136.00 FL	*- FL
12	1		*RH FRONT DOOR CHECKER	Bent	59.00 FL	*59.00 FL
13	1		*RH FRONT DOOR GLASS	Not Necessary	498.00 FL	*- FL
14	1		*RH FRONT DOOR GLASS OUTER MOULDING	Deformed	126.00 FL	*126.00 FL
15	1		*RH FRONT DOOR GLASS INNER CHANNEL MOULDING	Not Necessary	178.00 FL	*- FL
16	1		*RH FRONT DOOR WEATHER STRIPE	Necessary	159.00 FL	*159.00 FL
17	1		*RH FRONT DOOR POWER WINDOW MOTOR	Cracked	585.00 FL	*585.00 FL
18	1		*RH FRONT DOOR POWER WINDOW GEAR	Bent	298.00 FL	*298.00 FL
19	1		*RH FRONT DOOR INNER TRIM BOARD	Cracked	746.00 FL	*680.10 FL
20	1		*RH FRONT DOOR INNER TRIM BOARD SPEAKER	Cracked	299.00 FL	*299.00 FL
21	1		*RH FRONT DOOR WIRE HARNESS	Not Necessary	984.00 FL	*- FL
22	1		*RH FRONT DOOR BLACK STICKER	Necessary	79.00 FL	*79.00 FL
23	1		*RH FRONT DOOR STEP GARNISH	Deformed	113.00 FL	*113.00 FL
24	1		*RH FRONT DOOR RIM INNER SEAL	Not Necessary	125.00 FL	*- FL
25	1		*RH CENTER PILLAR OUTER PANEL	Bent	878.00 FL	*632.00 FL
26	1		*RH CENTER PILLAR INNER PANEL	Repair	1,355.00 FL	*- FL
27	1		*RH CENTER PILLAR BOTTOM GARNISH	Deformed	136.00 FL	*136.00 FL
28	1		*RH ROCKER PANEL OUTER	Bent	399.00 FL	*399.00 FL
29	1		*RH ROCKER PANEL INNER	Repair	658.00 FL	*- FL
30	1		*RH REAR DOOR	Bent	894.00 FL	*894.00 FL
31	1		*RH REAR DOOR OUTER HANDLER	Repair	145.00 FL	*- FL
32	1		*RH REAR DOOR OUTER HANDLER CHROME	Not Necessary	85.00 FL	*- FL
33	1		*RH REAR DOOR PROTECTOR	Cut	163.00 FL	*163.00 FL
34	1		*RH REAR DOOR PROTECTOR CHROME	Cut	126.00 FL	*126.00 FL
35	1		*RH REAR DOOR LOCK	Cracked	283.00 FL	*254.00 FL
36	1		*RH REAR DOOR LOCK CATCH	Not Necessary	32.00 FL	*- FL
37	2		*RH REAR DOOR HINGE	Bent	136.00 FL	*136.00 FL
38	1		*RH REAR DOOR CHECKER	Bent	59.00 FL	*59.00 FL
39	1		*RH REAR DOOR GLASS	Not Necessary	498.00 FL	*- FL
40	1		*RH REAR DOOR GLASS OUTER MOULDING	Deformed	126.00 FL	*126.00 FL
41	1		*RH REAR DOOR GLASS INNER CHANNEL MOULDING	Not Necessary	178.00 FL	*- FL
42	1		*RH REAR DOOR WEATHER STRIPE	Cut	159.00 FL	*159.00 FL
43	1		*RH REAR DOOR POWER WINDOW MOTOR	Jammed	585.00 FL	*585.00 FL
44	1		*RH REAR DOOR POWER WINDOW GEAR	Bent	298.00 FL	*298.00 FL
45	1		*RH REAR DOOR INNER TRIM BOARD	Cracked	746.00 FL	*365.53 FL
46	1		*RH REAR DOOR WIRE HARNESS	Not Necessary	984.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*RH REAR DOOR BLACK STICKER	Necessary	79.00 FL	*79.00 FL
48	1		*RH REAR DOOR STEP GARNISH	Necessary	113.00 FL	*113.00 FL
49	1		*RH REAR DOOR RIM INNER SEAL	Not Necessary	125.00 FL	*- FL
50	1		*RH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
51	1		*RH REAR DOOR INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*30.00 FS
52	1		*RH FRONT DOOR GLASS SOLAR FILM	Not Necessary	150.00 FS	*- FS
53	1		*RH REAR DOOR GLASS SOLAR FILM	Not Necessary	150.00 FS	*- FS
54	1		*RH DOOR PILLAR PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
55	1		*RH ROCKER PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					17,301.00	9,360.63
- List Item Discount on L Items 20.00/20.00% (S\$)					3,320.20	1,840.13
Total Parts (S\$)					13,980.80	7,520.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,800.00	1,000.00
2	LABOUR FOR SPRAYPAINTING	New	1,800.00	1,000.00
3	TO RUST PROOF / TUFF COAT ON REAR ACCIDENT AREAS	New	300.00	50.00
4	LABOUR FOR REMOVE & TRANSFER BOTH RH DOORS FITTING	New	200.00	60.00
5	WIRING CHECK	New	80.00	30.00
6	TO REMOVE & REFIX RH UPHOLSTERY / ROOF LINING TO FACILITATE THE REPAIR	New	300.00	100.00
7	TO CONDUCT WATER LEAKAGE	New	100.00	40.00
8	LABOUR FOR REMOVE & TRANSFER BOTH RH DOORS GLASS	New	300.00	60.00
Gross Labour Cost (\$\$)			5,880.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >