



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLQ4902P TYT WISH 1.8

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Bonnet			280.00		
2	Bonnet Hinge LH/RH @2*\$40			80.00		
1	Bonnet lock			60.00		
1	Bonnet logo badge			35.00		
1	Center grille			130.00		
1	Front bumper			180.00		
2	Front side retainer LH/RH @2*\$45			90.00		
1	Headlamp LH			400.00		
1	Radiator Top Garnish			70.00		
1	Support Panel (Repair refer to labor)			0.00		
		Part Items Total:		1325.00		
			10%	265.00		
				1590.00		
	<u>SPECIAL NETT ITEMS</u>					
1	Front bumper clips			35.00		
1	Front carplate with holder			35.00		
1	Center grille clips			25.00		
		SN Items Total:		95.00		
		Total Parts		1685.00		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLQ4902P TYT WISH 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	30.00	
	Labour Total :	1430.00	
	TOTAL (PARTS & LABOUR):	3115.00	