



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: repair@wahhong.sg

(89906235M)

Page No. 1

Vehicle No. SLQ4902P TYT WISH 1.8

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet		280.00	DT
2	Bonnet Hinge LH/RH @2*540		80.00	Xr
1	Bonnet lock		60.00	XSLC
1	Bonnet logo badge		35.00	/NCL
1	Center grille		130.00	XSLC
1	Front bumper		180.00	Xr
2	Front side retainer LH/RH @2*545		90.00	/NCL
1	Headlamp LH		400.00	/CFM
1	Radiator Top Garnish		70.00	XSLC
1	Support Panel (Repair refer to labor)		0.00	
Part Items Total:			1325.00	
			10% 265.00	
			1590.00	
SPECIAL NETT ITEMS				
1	Front bumper clips		35.00	20
1	Front carplate with holder		35.00	15
1	Center grille clips		25.00	
SN Items Total:			95.00	
Total Parts			1685.00	

885 S



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLQ4902P TYT WISH 1.8

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	300
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	30.00	20
Labour Total :		1430.00	
TOTAL (PARTS & LABOUR):		3115.00	

Thevan@Lthauto.com

82235769

2/3/22 1300

OD excess: TBC

4 days wp

Pls bfr paint photo

U/S

1400

1678.5
1340.41
1350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: