

Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg (199806235M)

Vehicle No.

SLQ4902P TYT WISH 1.8

Page No. 2

s/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT	
	LABOUR	800.00	400	
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	800.00		
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00	300	
3	To remove/refix/replace wiring system at accident damaged area and check for all electrical proper function	30.00	20	
	Labour Total :	1430.00		
	TOTAL (PARTS & LABOUR): 3115.00			

Theyan@ Lthauto. low 82235769 7/3/22 1300 OD extess: TBC 4 days wp The both paint photo lump sum after

after repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Vehicle No.

SLQ4902P TYT WISH 1.8

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)	,		
1 2 1 1 1 2 1	Bonnet Bonnet Hinge LH/RH @2*\$40 Bonnet lock Bonnet logo badge Center grille Front bumper Front side retainer LH/RH @2*\$45 Headlamp LH Radiator Top Garnish		280.00 / 80.00 K 60.00 K 35.00 / 130.00 K 180.00 K 90.00 / 400.00 / 0.00	suc ncc svc V ncc (19
1	SPECIAL NETT ITEMS Front bumper clips Front carplate with holder Center grille clips	Part Items Total: SN Items Total:	1325.00 265.00 1590.00 35.00 35.00 25.00	20
		Total Parts	1685.00	