

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2203-112
DATE : 1-Mar-2022
POLICY NO. : FWD PNPV2020-0001754-02
VEHICLE REG. NO. : **SMJ1193M**
VEHICLE MAKE : SWIFT SPORTS 1.4L TURBO MANUALTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Rear Bumper Sport Version	1	\$ 750.00	\$ 750.00
2	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 30.00	\$ 30.00
4	Rear Bumper Retainer LH	1	\$ 30.00	\$ 30.00
6	Rear Bumper Extension LH (7)	1	\$ 45.00	\$ 45.00
7	Rear Bumper Garnish LH (3)	1	\$ 45.00	\$ 45.00
8	Rear Fog Lamp	1	\$ 65.00	\$ 65.00
9	Rear License Lamp	1	\$ 45.00	\$ 45.00
11	Rear Fender LH	1	\$ 550.00	\$ 550.00
12	Rear Fender Shield LH	1	\$ 180.00	\$ 180.00
13	Rear Fender RH	1	\$ 550.00	\$ 550.00
14	Rear Fender Shield RH	1	\$ 180.00	\$ 180.00
15	Rear Fender Clips	10	\$ 5.00	\$ 50.00
16	Rear Fender Guard Garnish RH	1	\$ 40.00	\$ 40.00
17	Rear Fender Guard Garnish LH	1	\$ 40.00	\$ 40.00
18	Rear Tailgate Door	1	\$ 880.00	\$ 880.00
19	Rear Tailgate Door WeatherStrip	1	\$ 90.00	\$ 90.00
20	Rear Tailgate Door Inner Trim	1	\$ 220.00	\$ 220.00
21	Rear Tailgate Balancer RH - 81800-63812	1	\$ 150.00	\$ 150.00
22	Rear Tailgate Balancer LH - 81800-63822	1	\$ 150.00	\$ 150.00
23	Rear Tailgate Door Lock Handle (Red)	1	\$ 50.00	\$ 50.00
24	Rear Tailgate Door Lock	1	\$ 200.00	\$ 200.00
25	Rear Tailgate Door Lock Latch	1	\$ 40.00	\$ 40.00
26	Rear Tailgate Spoiler Assy	1	\$ 600.00	\$ 600.00
27	Rear Emblem - S (Chrome)	1	\$ 40.00	\$ 40.00
28	Rear Emblem - Swift (Chrome)	1	\$ 45.00	\$ 45.00
29	Rear Emblem - Sports (Chrome Red)	1	\$ 45.00	\$ 45.00
30	Rear / End Panel Garnish	1	\$ 80.00	\$ 80.00
31	End Panel	1	\$ 350.00	\$ 350.00
32	Spare Tyre Board Cover	1	\$ 120.00	\$ 120.00
33	Rear Tools Sponge Box/Tray	1	\$ 90.00	\$ 90.00

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2203-112
DATE : 1-Mar-2022
POLICY NO. : FWD PNPV2020-0001754-02
VEHICLE REG. NO. : SMJ1193M
VEHICLE MAKE : SWIFT SPORTS 1.4L TURBO MANUALTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
35	Rear Tail Lamp Assy RH	1	\$ 720.00	\$ 720.00
36	Rear Tail Lamp Assy LH	1	\$ 720.00	\$ 720.00
37	Rear Tail Lamp High Mount Stop	1	\$ 140.00	\$ 140.00
38	Rear Taillamp Inner Housing LH	1	\$ 90.00	\$ 90.00
39	Rear Exhaust Tail Chrome Pipe LH	1	\$ 200.00	\$ 200.00
42	Rear Exhaust Muffler	2	\$ 720.00	\$ 1,440.00
43	Rear Exhaust Rubber Mount	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 9,170.00
	<u>SPECIAL NETT</u>			
44	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
45	Rear Licence Plate	1	\$ 35.00	\$ 35.00
46	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 275.00
	<u>LABOUR</u>			
47	Spray painting Rear Bumper, Tailgate, Both Rear Fender Including Blending	1	\$ 1,000.00	\$ 1,000.00
48	Remove, Replace and Repair Accident Affected Area	1	\$ 1,000.00	\$ 1,000.00
49	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
50	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
51	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 100.00	\$ 100.00
52	Remove and Refit Rear Windscreen	1	\$ 100.00	\$ 100.00
53	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
54	Anti-Rust Tuff Coat	1	\$ 40.00	\$ 40.00
55	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,570.00
Amount Before Excess				\$ 12,015.00
Add GST @ 7%				841.05
Total Amount Payable				\$ 12,856.05

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.